## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

**David Martin** 

Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director Oil Conservation Division



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

30-Jun-14

HOBBS OCD

JUL 01 2014

THREE FORKS RESOURCES, LLC

1515 WAZEE SUITE 350 DENVER CO 80202

RECEIVED

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

CS CAYLOR No.004

F-6-17S-37E

30-025-05425-00-00

**LETTER OF VIOLATION - Inspection** 

Inspection Date

Type Inspection

Inspector

\*Significant Violation? Non-Compliance? Corrective

Inspection No.

06/26/2014

Routine/Periodic

Mark Whitaker

Yes

No

Action Due By: 8/25/2014 iMAW1417757687

Comments on Inspection:

DO NOT RELEASE. Two wire rope anchors south of dry hole marker. A pile of wire rope off NW corner of location. Dry hole marker not complete. Power disconnects and meter base have not been removed from pole on north side of location. NEED TO REMOVE ANCHORS, PILE OF WIRE ROPE, CORRECT DRY HOLE MARKER, AND REMOVE POWER DISCONNECTS AND METER BASE FROM POWER POLE. OPERATOR SHOULD ALSO BE CERTAIN THAT FLOW LINE HAS BEEN FLUSHED TO BATTERY AND DISCONNECTED FROM HEADER.

1st notice.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977 BP SO . 69 O7/01/14 SO . Mailed From 88240 SO . Mailed From 88240

THREE FORKS RESOURCES, LLC 1515 WAZEE SUITE 350 DENVER, CO. 80202