Submit 3 Copies To Appropriate District State of New Mexico		Form C-103
Office Energy, Minerals and Natural Resources		WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II OIL CONSERVATION DIVISION		30-025-37243
1301 W. Grand Ave., Artesia, NM 88210 1625 N. FRENCH DRIVE		5. Indicate Type of Lease STATE ☐ FEE ☒
District III HOBBS, NM 88240 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
<u>District IV</u>		
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR		NEDU
SUCH PROPOSALS.)		8. Well Number
1. Type of Well:		
Oil Well Gas Well Other 2. Name of Operator		721 9. OGRID Number
APACHE CORPORATION		873
3. Address of Operator 6120 S. YALE, STE. 1500 TULSA, OK 74136		10. Pool name or Wildcat Blinebry O&G Drinkard; Tubb O&G
4. Well Location		
Unit Letter M: 1310 feet from the S line and 330 feet from the W line		
Section 15 Township 21S Range 37E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,445'		
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)		
Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well		
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;		
feet from theline andfeet from theline	ne	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASKING		
TEMPORARILY ABANDON		ILLING OP SE CONTROL OF PLUG AND SE CONTROL OF SE CONTROL
PULL OR ALTER CASING	CASING TEST AI	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
OTHER:	OTHER: SPUD	, SURF. CSG., TO LOG, PROD. CSG.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE		
RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 9/16/05 SPUD, DRILL & SURVEY TO 585'.		
9/17/05- DRILL & SURVEY FROM 585'-6850 (TD). R.U. & RUN 8.625 CASING. WORK CSG. LAY DOWN 1 JT. CSG & INSTALL WASH OUT SUB. WASH DOWN 9/29/05 LAST 3 JTS. 175'. CMT W/ BJ CMT W/ 375 SX 35:65 POZ W/ GEL + 2%CACI=25# CF = 125 BBLS. 12.7# SLURRY W/1.88 YEILD - TAIL W/ 200 SX CLASS C + 2% CACL + 125# CF = 48 BBLS 14.8# SLURRY W/1.35 YIELD - PLUG BUMPED & HELD - CIRC 119 SX CMT. TO PIT = 40 BBLS. PLUG DOWN @ 22:30 RIG DOWN BJ CEMENTERS. W OC. CUT OFF CONDUCTOR & 8.625 CSG WELD ON HEAD & TEST TO 400 PSI. NIPPLE UP BOP & CHOKE, TESTING 3 rd PARTY BLINDS, CSG., PIPE RAMS, CHOKE, KELLY COCK, DART VALVE, =500 LOW 2000 HIGH OK. TIH W/ BIT #2 TOP OF CMT. AT 1215'. DRILL- CMT, PLUG & SHOE. SURVEY @ 2456' = MISRUN RUN NEXT KELLY DOWN. DRILL - 2993' - 3468'. CIRC, SERV. RIG, CHANGE OIL & FILTERS ON SWIVEL MOTOR, SURVEY @ 3436' = .50. DRILL - 2993' - 3468'. DRILL & DRILLING LINE - INSTALL NEW LINE THROUGHOUT SYSTEM. DRILL - 5396' - 5477'. TOH FOR BIT # 3. TRIP IN HOLE W/ BIT # 3. WASH LAST 5 JTS TO BTM. DRILL - 5477' - 5715'. DRILL 6660' - 6850' TD WELL @ 11:00 AM. SURVEY @ 6835' = 1. CIRCULATE TO RUN LOGS. TOH FOR LOGS. OPEN HOLE LOGS LOGGING WELL. MOVE DP & DC MOVE 5.50 CSG TO RUN. SAFETY MEETING RIG UP CASING CREW. RUN 5.50" CSG 28 CENTRALIZERS. WASH 40' TO BTM CIRCULATE CSG. BJ CMT SHOE @ 6850' - FC @ 8606' CMT W/		
900 SX 50-50 POZ C GEL + 5% SALT + .125 # CF+ 5/10 % FL52 = 392 BBLS 11.8 SLURRY W/ 2.45 YIELD & 400 SX 50-50 POZ C GEL 5% SALT + 6/10 % FL25 = 92 BBLS 14.2 SLURRY W/ 1.29 YIELD - DISPLACE W/ 158 BBLS 2% KCL WATER - PLUG BUMPED & HELT - CIRC 125 SX TO PIT. NIPPLE DOWN SET SLIPS CUT OFF CSG RIG DOWN MOVE RIG UP. RIG RELEASED 9/29/2005		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .		
SIGNATURE JANA WILLIAMS TITLE DR. DEPT. CLERK DATE 10/11/05		
Type or print name LANA WILLIAMS E-mail address: lana.williams@apachecorp.com Telephone No. 918-491-4980		
(This space for State use) APPPROVED BY TITLE DATE Conditions of approval, identity		
APPPROVED BY TITLE	-WENGINEED D	ATE
Conditions of approval, if any:		OCT 2 1 2005