Submit I Copy To Appropriate District Office	State of Ne		Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and	l Natural Resources	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-12494	
<u>District III</u> – (505) 334-6178	1220 South St	. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, N	IM 87505	STATE FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	,		6. State Off & Gas Lease No.	
87505	CES AND REPORTS ON W	/ELLC	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLIC			27	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	HOBBS OCD	8. Well Number	
1. Type of Well. Off Well	Gas well Other		12/	
2. Name of Operator		JUL 18 2014	9. OGRID Number: 157984	
Occidental Permian Ltd.	<u></u>	JUL 10 50.		
3. Address of Operator			10. Pool name or Wildcat	
2611 State Hwy 214 Denver Ci	ty, 1X /9323	RECEIVED	Hobbs (G/SA)	
4. Well Location				
		line and412		
Section 27	Township 18S	Range 38E	NMPM Lea County	
	11. Elevation (Show wheth	er DR, RKB, RT, GR, etc.		
	3636' GR			
12. Cheek Ammeniste Day to Indicate Notine of Nation Depart on Other Date				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐				
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐				
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐				
DOWNHOLE COMMINGLE				
OTHER:	Г	OTHER:	П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or rec	ompletion.			
		During this pro	cedure we plan to use	
			p system with a steel	
the diodes to p			contents to the required	
CO and Three 1'S are a second to the control of the				
4. Run ESP equipment disposal per ODC Rule			DC Nule 13.13.17	
5. RDPU and clean location				
			·	
				
Spud Date:	Rig Rele	ase Date:		
<u> </u>				
I hereby certify that the information	above is true and complete to	the best of my knowledg	ge and belief.	
/1	,			
SIGNATURE (State State TITLE Lift Specialist DATE 7/16/2014 M				
SIGNATORE DATE TITLE EIN SPECIALIST DATE TITLE IN SPECIALIST				
Type or print name Steve Snead E-mail address: steve snead@oxy.com PHONE: 806-592-6312				
For State Use Only A A				
MAI DAKA A A A A A A A A A A A A A A A A A				
APPROVED BY:				
Conditions of Approval (if any):				
UL 2 2 2 114				