

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)		WELL API NO. 30-025-31622
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator LEGACY RESERVES OPERATING LP		6. State Oil & Gas Lease No.
3. Address of Operator PO BOX 10848, MIDLAND, TX 79702		7. Lease Name or Unit Agreement Name NEW MEXICO STATE
4. Well Location Unit Letter <u>G</u> : <u>1980</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>EAST</u> line Section <u>32</u> Township <u>14S</u> Range <u>34E</u> NMPM County <u>LEA</u>		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4131' GL		9. OGRID Number 240974
		10. Pool name or Wildcat TRES PAPALOTES PENN

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
DOWNHOLE COMMINGLE ☐			
CLOSED-LOOP SYSTEM ☒			
OTHER: ☐		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Estimated Start Date: 08/18/14

1. Set CIBP @ 10,300' w/35' of cmt. 25' above top of current Bough A perf @ 10,325'.
2. Tag CIBP @ 10,300'.
3. Re-complete in Abo.
4. Repair 5 1/2" production casing.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Craig Sparkman TITLE OPERATIONS ENGINEER DATE 07/21/2014

Type or print name CRAIG SPARKMAN E-mail address: _____ PHONE: 432-689-5200

For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 7/28/2014

Conditions of Approval (if any)

JUL 29 2014

[Signature]



New Mexico State #1

LOCATION: 1980' FNL & 1980' FEL, Sec 32, T14S, R34E

Current Wellbore

FIELD: Tres Papalotes Penn

GL: 4131'

LATEST UPDATE: 3/14/2014

COUNTY: Lea


KB: 4144'

BY: CSPARKMAN

STATE: New Mexico

SPUD DATE: 07/25/1992

API No: 30-025-31622





New Mexico State #1

LOCATION: 1980' FNL & 1980' FEL, Sec 32, T14S, R34E

Proposed Wellbore

FIELD: Tres Papalotes Penn

GL: 4131'

LATEST UPDATE: 7/21/2014

COUNTY: Lea

KB: 4144'

BY: CSPARKMAN

STATE: New Mexico

SPUD DATE: 07/25/1992

API No: 30-025-31622

