

State of New Mexico

Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey, Division Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

18-Aug-14

MOREXCO INC
P. O. BOX 51208
MIDLAND TX 79710

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

AIRSTRIP A STATE No.001		K-15-18S-34E		30-025-29902-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/18/2014	Routine/Periodic	Mark Whitaker	Yes	No	10/17/2014	iMAW1423048149
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Rule 19.15.16.8. Well signs do not reflect current operator at well or battery. NEED TO REPLACE WELL SIGNS THAT COMPLY WITH CURRENT RULES. SIGN AT BATTERY SHOULD LIST EMERGENCY CONTACT NUMBER. 1st notice.						

AIRSTRIP A STATE No.002		L-15-18S-34E		30-025-32658-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/18/2014	Routine/Periodic	Mark Whitaker	Yes	No	10/17/2014	iMAW1423048289
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: Rule 19.15.16.8. Well signs do not reflect current operator. NEED TO REPLACE WELL SIGNS THAT COMPLY WITH CURRENT RULES. 1st notice.						

Rule 19.15.16.8
Each sign shall show operator's name, property name, well number, location by footage, unit letter section, township, range, and API number

AUG 19 2014

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.


Sincerely,


COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER 015H14150977
\$0.48
08/18/14
Mailed From 88240
US POSTAGE

MOREXCO INC
PO BOX 51208
MIDLAND, TX 79710