

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-01829	1
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E-2064	
7. Lease Name or Unit Agreement Name South Four Lakes Unit	
8. Well Number 3	
9. OGRID Number 151323	
10. Pool name or Wildcat Four Lakes Penn	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 4143	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Pride Energy Company

3. Address of Operator
PO Box 701950, Tulsa, OK 74170-1950

4. Well Location
 Unit Letter **D**: **660** feet from the **N** line and **660** feet from the **W** line
 Section **1** Township **12-S** Range **34-E** NMPM County **Lea**

HOBBS OCD
AUG 21 2014
RECEIVED

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING PE <input checked="" type="checkbox"/> P&A NR P.M. TE <input checked="" type="checkbox"/> INT TO P&A PL <input type="checkbox"/> CSNG DI <input type="checkbox"/> TA OTHER: <input type="checkbox"/>	P&A R _____] _____] _____] CHG Loc _____ RBDMS CHART _____ OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
---	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7:14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/01/14 MIRU plugging equipment. Dug out cellar. ND wellhead. NU BOP. RIH w/ gauge ring to 1100'. POH w/ gauge ring. Set 7" packer @ 30' and pressured up on casing. Held 1000 psi. 08/04/14 RIH w/ 3 3/4 gauge ring to 5640. POH w/ gauge ring. RIH w/ tbg to 5640 and circulated hole w/ mud laden fluid. Spotted 35 sx cement @ 5640'. (per Mark Whitiker OCD). WOC. 08/05/14 Tagged plug @ 5355'. POH to 4250. Spotted 50 sx cement @ 4250-3943. WOC. Tagged plug @ 3975'. Spotted 50 sx cement @ 2850-2543. POH to 2000'. Spotted 50 sx cement @ 2000-1693. POH w/ tbg. 08/06/14 Tagged plug @ 1698'. ND BOP. Spotted 80 sx cement @ 450 - surface. Riggged down moved off. 08/08/14 Moved in welder and backhoe. Dug out cellar. Cut off wellhead. Welded on "Above Ground Dry Hole Marker". Backfill cellar. Removed deadment. Cleaned location and moved off.

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kyle Young TITLE _____ DATE 8/18/2014
 Type or print name Kyle Young E-mail address: kyley@pride-energy.com PHONE: 918-524-9200
For State Use Only
 APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 8/21/2014
 Conditions of Approval (if any): _____

AUG 21 2014 



HOBBS OCD

AUG 21 2014

RECEIVED

August 18, 2014

New Mexico Oil Conservation Division
1625 N. French Drive
Hobbs, NM 88240

VIA Certified Mail
Return Receipt #:

91 7199 9991 7034 2234 9541

ATTN: Maxey Brown
District Supervisor

RE: Form C-103 Subsequent Report of Plugging and Abandoning

1. South Four Lakes Unit, Well No. 003
Unit Letter D
Section 1-12S-34E
2. South Four Lakes Unit, Well No. 001
Unit Letter B
Section 2-12S-34E

Mr. Brown:

In reference to the above described wells, please find attached a Form C-103 (Subsequent Report of Plugging and Abandoning), for each of these wells. Upon your review and approval, please e-mail a copy of the approved Form C-103s to my attention.

If you have any questions, please contact me by phone at (918) 524-9200 or email at kyley@pride-energy.com.

Thank you in advance for your help.

Sincerely,

Kyle Young

Pride Energy Company
P. O. Box 701950 Tulsa, Oklahoma 74170
Phone: 918.524.9200 Fax: 918.524.9292