

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-30891
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CIMAREX ENERGY CO. OF COLORADO		6. State Oil & Gas Lease No.
3. Address of Operator 600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701		7. Lease Name or Unit Agreement Name MITCHELL "16" STATE
4. Well Location Unit Letter A : 469 feet from the NORTH line and 554 feet from the EAST line Section 16 Township 18S Range 32E NMPM LEA County		8. Well Number 002
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,799' - GR		9. OGRID Number 162683
		10. Pool name or Wildcat YOUNG; WOLFCAMP

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING
P&A NR ☒ P&A R ☐
INT TO P&A ☐ COMP ☐
CSNG ☐ CHG Loc ☐
TA ☐ RBDMS CHART ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: WELL PLUGGED AND ABANDONED 09/21/14.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

09/11/14: SET 5-1/2" CIBP @ 10,450'; CIRC. WELL W/ PXA MUD; PRES. TGEST 5-1/2" CSG. TO 750# - HELD OK.
09/13/14: PUMP 30 SXS. CMT. @ 10,450'; WOC - DID NOT TAG CMT.; PUMP 30 SXS. CMT. @ 10,450'; WOC.
09/14/14: DID NOT TAG CMT.; PUMP SAND X 50 SXS. CMT. ON TOP OF CIBP @ 10,450'; WOC.
09/15/14: TBG. STUCK; CUT X POOH W/ TBG. @ 8,395'.
09/16/14: SET 5-1/2" CIBP @ 8,385' (PER OCD); PRES. TEST CSG. TO 700#-HELD OK; PUMP 25 SXS. CMT. @ 8,385'; WOC.
09/17/14: DID NOT TAG CMT.; PRES. TEST CSG. TO 900#-HELD OK; PUMP 50 SXS. CMT. @ 8,385'; WOC X TAG @ 8,082'.
09/18/14: PUMP 25 SXS. CMT. @ 6,570'-6,510'; PUMP 25 SXS. CMT. @ 5,491'; WOC X TAG CMT. @ 5,309' (OK'D BY OCD);
PUMP 25 SXS. CMT. @ 4,500'-4,360'; PUMP 25 SXS. CMT. @ 2,960'; WOC X TAG CMT. @ 2,650'.
09/19/14: CUT 5-1/2" CSG. @ 2,150' - NOT FREE; PRES. UP ON CSG. CUT; PUMP 35 SXS. CMT. @ 2,200'; WOC X TAG @ 2,017'.
09/20/14: PERF. SQZ. HOLES @ 1,215' - PRES. UP; PUMP 30 SXS. CMT. @ 1,265'; WOC X TAG @ 950'; PERF. X SQZ. 35 SXS.
CMT. @ 401'; WOC X TAG CMT. PLUG @ 224'.
09/21/14: PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 30 SXS. CMT. @ 100'-3'; DIG OUT X CUT OFF WELLHEAD 3'
B.G.L.; VERIFY CMT. TO SURF.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.

MIRU: 09/06/14

RDMO: 09/21/14

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David A. Eyler TITLE: AGENT DATE: 09/22/14

Type or print name: DAVID A. EYLER E-mail address: DEYLER@MILAGRO-RES.COM PHONE: 432.687.3033

For State Use Only

APPROVED BY: Mary Brown TITLE: Dist Supervisor DATE: 9/24/2014

Conditions of Approval (if any)

SEP 25 2014