

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-03403
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. 1149417
7. Lease Name or Unit Agreement Name State AK Warrior
8. Well Number 2
9. OGRID Number 180387
10. Pool name or Wildcat Eumont: Yates-7 Rivers-Queen

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3598' KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Finley Resources, Inc.

3. Address of Operator
1308 Lake Street, Ste. 200, Fort Worth, Texas 76102

4. Well Location
Unit Letter P : 4214' feet from the North line and 330' feet from the East line
Section 3 Township 21S Range 35E NMPM County Lea


12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3680'
Set CIBP @ +/- 3350'. Spot 25 sx. cmt. Tag to verify. Circulate hole with 9.5#/gal. salt gel mud. Determine freepoint on 5 1/2" casing. Cut and pull 5 1/2" within 100' of freepoint or +/- 1800'. Spot 100' cement from 50' below cut or 1850' to 1750' - Tag to verify. Spot 100' cement from 395' to 295'. Spot 60' surface plug. Cut off excess 8 5/8" casing and weld dry hole marker.

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternate OGD-approved plan ☐.

SIGNATURE James L. Nance TITLE: Production & Operations Engineer DATE 9/20/05

Type or print name James L. Nance E-mail address: jim.nance@finleyresources.com Telephone No. (817) 231-8727
For State Use Only

APPROVED BY: Larry W. Wank TITLE: SC FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____
Conditions of Approval (if any): _____

OCT 24 2005

State AK #2

4214' FNL, 330' FEL, Sec 3 P
T21S, R35E Lea Co., NM
Eumont Field completion Date: 12/18/56

KB 3598' (0')
API # 30 025 03403
NM ID 1149417

