

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-025-21710 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name PEARSALL QUEEN SAND UNIT |
| 8. Well Number 3 |
| 9. OGRID Number 240974 |
| 10. Pool name or Wildcat PEARSALL; QUEEN |

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
LEGACY RESERVES OPERATING LP

3. Address of Operator
PO BOX 10848, MIDLAND, TX 79702

4. Well Location
Unit Letter P : 660 feet from the SOUTH line and 660 feet from the EAST line
Section 32 Township 17S Range 32E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3885' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

State approval is respectfully requested to lay down all the current rods, pump and tubing equipment; install a cast iron bridge plug (CIBP) on wireline at 3500' above the current Queen Sand perforations from 3553'-3587'; dump 35' of cement on top of the CIBP using a dump bailer for PBTD 3465'; and perform a mechanical integrity test (MIT) to 500 psig for 30 minutes on the 5 1/2" production casing. If a successful MIT is obtained, we propose that the well be temporarily abandoned pending the evaluation of possible recompletion or a proposal to plug and abandon the wellbore. If the well fails the MIT test, a proposal to plug and abandon the wellbore will be promptly submitted for approval.

Current and proposed wellbore diagrams are attached.

Condition of Approval: notify

OCD Hobbs office 24 hours

prior of running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Pina TITLE REGULATORY TECH DATE 10/10/2014

Type or print name LAURA PINA E-mail address: lpina@legacylp.com PHONE: 432-689-5200

For State Use Only

APPROVED BY: Malay Brown TITLE Dist Supervisor DATE 10/14/2014

Conditions of Approval (if any):

OCT 17 2014



PEARSALL QUEEN SAND UNIT #3

Current wellbore diagram

FIELD: Pearsall Queen

COUNTY: Lea

STATE: New Mexico

GL: 3885'

KB: Unknown

SPUD DATE: 11/25/65


LATEST UPDATE: 10/08/2013

BY: MAL

API No: 30-025-21710

Location:

SHL: 660' FSL & 660' FEL, Sec 32, T17S, R32E





PEARSALL QUEEN SAND UNIT #3
PROPOSED wellbore diagram

FIELD: Pearsall Queen
COUNTY: Lea
STATE: New Mexico

GL: 3885'
KB: Unknown
SPUD DATE: 11/25/65

LATEST UPDATE: 10/08/2013
BY: MAL
API No: 30-025-21710

Location:

SHL: 660' FSL & 660' FEL, Sec 32, T17S, R32E

