Office	State of New Me			Form C-103
District I – (575) 393-6161	Energy, Minerals and Natu	ral Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			ELL API NO. 30-025-41562	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION	5. Indicate Type of Lease	
District III – (505) 334-6178 1220 South St. Francis Debs OCD 000 Rio Brazos Rd., Aztec, NM 87410		ICIS ACBBS OCU	STATE STEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87		State Oil & Gas Leas	
1220 S. St. Francis Dr., Santa Fe, NM		OCT 27 2014	VO-8421	
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7	Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR DROPO	SALS TO DOLLL OR TO DEEDEN OR PLI	IG BACK TO A	Tango BTP State Co	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FO	OR SUCH RECEIVED 8.	Well Number	
1. Type of Well: Oil Well	Gas Well Other		4H	
2. Name of Operator		9.	OGRID Number	
Yates Petroleum Corporation			025575	
3. Address of Operator		10	10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210			Wildcat; Bone Spring	g
4. Well Location				
Unit Letter A :	200 feet from the North			East line
Unit Letter P	feet from the South	line and671	feet from the	East line
Section 36			MPM Lea	County
	11. Elevation (Show whether DR,			
	3,690	GR		
			0.1	
12. Check A	Appropriate Box to Indicate N	ature of Notice, Reg	port or Other Data	
NOTICE OF IN	ITENTION TO:	SUBSE	QUENT REPOR	T OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	_	RING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLII		_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JO	<u>=</u>	_
DOWNHOLE COMMINGLE	· · · · · · · · · · · · · · · · · · ·			
CLOSED-LOOP SYSTEM	· 			
CLOSED-LOOP SYSTEM OTHER:		OTHER: Completion		
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp	oleted operations. (Clearly state all posts) SEE BULE 10.15.7.14 NMAG	pertinent details, and gi	ve pertinent dates, incl	luding estimated date
OTHER: 13. Describe proposed or compostarting any proposed we	ork). SEE RULE 19.15.7.14 NMAC	pertinent details, and gi	ve pertinent dates, incl	luding estimated date
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp	ork). SEE RULE 19.15.7.14 NMAC	pertinent details, and gi	ve pertinent dates, incl	luding estimated date
OTHER: 13. Describe proposed or compostarting any proposed we	ork). SEE RULE 19.15.7.14 NMAC	pertinent details, and gi	ve pertinent dates, incl	luding estimated date
OTHER: 13. Describe proposed or compostarting any proposed we	ork). SEE RULE 19.15.7.14 NMAC	pertinent details, and gi	ve pertinent dates, incl	luding estimated date
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recomposed completion.	ork). SEE RULE 19.15.7.14 NMAC completion.	pertinent details, and gi	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed compl	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open	pertinent details, and gith. For Multiple Complete. For Multiple Complete.	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed compl	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in	pertinent details, and given for Multiple Complete. For Multiple Complete for Multiple C	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes)	pertinent details, and given the complete. For Multiple Complete. For Multiple Complete to sleeve at 15,767 hibitor.). Acidized Bone Springer.	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed compl	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes)	pertinent details, and given the complete. For Multiple Complete. For Multiple Complete to sleeve at 15,767 hibitor.). Acidized Bone Springer.	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes)	pertinent details, and given the complex of the sleeve at 15,767 hibitor. The complex of the sleeve at 15,767 hibitor. The complex of the sleeve at 15,767 hibitor.	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes)	pertinent details, and given the complex of the sleeve at 15,767 hibitor. The complex of the sleeve at 15,767 hibitor. The complex of the sleeve at 15,767 hibitor.	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes)	pertinent details, and given the complex of the sleeve at 15,767 hibitor. The complex of the sleeve at 15,767 hibitor. The complex of the sleeve at 15,767 hibitor.	ve pertinent dates, incletions: Attach wellbor	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete. For Multiple Complete to sleeve at 15,767 hibitor. 1. Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored. 7. Pumped 1500 galloring 11,566' – 15,767'	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open of the CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes)	pertinent details, and given the complete. For Multiple Complete to sleeve at 15,767 hibitor. 1. Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored. 7. Pumped 1500 galloring 11,566' – 15,767'	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete. For Multiple Complete to sleeve at 15,767 hibitor. 1. Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored. 7. Pumped 1500 galloring 11,566' – 15,767'	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open with CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 14,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete complete. For Multiple Complete complete to the sleeve at 15,767 hibitor. 1). Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored at the second of the se	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open with CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 14,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete complete. For Multiple Complete complete to the sleeve at 15,767 hibitor. 1). Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored at the second of the se	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open with CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 14,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete complete. For Multiple Complete complete to the sleeve at 15,767 hibitor. 1). Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored at the second of the se	luding estimated date re diagram of ns 15% NEFE acid.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete of the sleeve at 15,767 hibitor. Details and given the complete of the sleeve at 15,767 hibitor. Details and complete of the sleeve at 15,767 hibitor. Details and complete of the sleeve at 15,767 hibitor. Details and given the sleeve at	ve pertinent dates, incletions: Attach wellbored attach wellbored. 7. Pumped 1500 gallored at 15,767' very service at 14.	luding estimated date re diagram of ns 15% NEFE acid. with 67,500 gallons
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete complete. For Multiple Complete complete to the sleeve at 15,767 hibitor. 1). Acidized Bone Spring conoprop sand.	ve pertinent dates, incletions: Attach wellbored attach wellbored. 7. Pumped 1500 gallored at 15,767' very service at 14.	luding estimated date re diagram of ns 15% NEFE acid. with 67,500 gallons
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recomposed completion or recomposed completion or recomposed completion or recomposed complet	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open with CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E	pertinent details, and given the complete of the sleeve at 15,767 hibitor. Details and given the complete of the sleeve at 15,767 hibitor. Details and complete of the sleeve at 15,767 hibitor. Details and complete of the sleeve at 15,767 hibitor. Details and given the sleeve at	ve pertinent dates, incletions: Attach wellbored betions: Attach wellbored by the second of the seco	luding estimated date re diagram of ns 15% NEFE acid. with 67,500 gallons
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E Rig Release Da above is true and complete to the because of the second seco	pertinent details, and given the complete of the sleeve at 15,767 hibitor. Details and given the complete of the sleeve at 15,767 hibitor. Details and complete of the compl	ve pertinent dates, incletions: Attach wellbored betions: Attach wellbored by the second of the seco	luding estimated date re diagram of ns 15% NEFE acid. with 67,500 gallons October 24, 2014
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recomposed completion or recomposed completion or recomposed completion or recomposed complet	ork). SEE RULE 19.15.7.14 NMAC completion. O psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E Rig Release Da above is true and complete to the because of the scale in	pertinent details, and given the complete of the sleeve at 15,767 hibitor. Acidized Bone Spring conoprop sand. The conoprop sand the complete of my knowledge and control of my knowledge and contro	ve pertinent dates, incletions: Attach wellbored 1500 gallor gall,566' – 15,767' value distribution distribut	luding estimated date re diagram of ns 15% NEFE acid. with 67,500 gallons October 24, 2014
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recomposed completion or recomposed completion or recomposed completion or recomposed complet	ork). SEE RULE 19.15.7.14 NMAC completion. 0 psi. 5-1/2" casing to 1000 psi, ok. Open ith CRW-132 corrosion and scale in Spring 11,566' – 15,670' (468 holes 4,348,254# 20/40 RCS and 30/50 E Rig Release Da above is true and complete to the because of the second seco	pertinent details, and given the complete of the sleeve at 15,767 hibitor. Details and given the complete of the sleeve at 15,767 hibitor. Details and complete of the compl	ve pertinent dates, incletions: Attach wellbored betions: Attach wellbored by the second of the seco	luding estimated date re diagram of ns 15% NEFE acid. with 67,500 gallons October 24, 2014