

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
 ConocoPhillips Company

3a. Address
 P. O. Box 51810 Midland TX 79710-1810

3b. Phone No. (include area code)
 (432)688-6884

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
 UL "L", 1980' FSL & 660' FWL
 Sec. 15, T-20-S, R-37-E

5. Lease Serial No.
 LC 031621B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
 Britt B #14

9. API Well No.
 30-025-06113

10. Field and Pool, or Exploratory Area
 Monument; Paddock

11. County or Parish, State
 Lea
 New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Location
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Final
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	Abandonment

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

All reclamation work has been completed; this location is ready for Final Abandonment inspection.

It is our understanding the BLM will continue to monitor the surface restoration, vegetative growth to 20%, of this abandoned well site until established evenly across the location and restored to a condition similar to its original state.

14. I hereby certify that the foregoing is true and correct
 Name (Printed/Typed)
 Celeste G. Dale

Title
 Regulatory Specialist

Signature
Celeste G. Dale

Date
 06/14/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by
James G. Burns

Title
 SPEET

Date
 11-4-14

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office
 CFD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

MWB/ocd 11/12/2014

Red & Seal
NOV 12 2014
ym