

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBOCKOCD
 DEC 10 2014
 RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30 025 42190
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>Dry Hole</u>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Primero Operating, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 1433, Roswell, NM 88202-1433		7. Lease Name or Unit Agreement Name Exuma Flats
4. Well Location Unit Letter <u>K</u> ; <u>1980</u> feet from the <u>S</u> line and <u>2140</u> feet from the <u>W</u> line Section <u>7</u> Township <u>16S</u> Range <u>38E</u> NMPM Lea County		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3761 G		9. OGRID Number 018100
		10. Pool name or Wildcat WC-025, G-08, S163807K: Strawn

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: <input type="checkbox"/>		E-PERMITTING P&A NR <u>P.M.</u> P&A R _____ INT TO P&A _____ COMP _____ CSNG _____ CHG Loc _____ TA _____ RBDMS CHART _____ OTHER: _____
---	--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

We TDD this well yesterday and logged last night. We have determined that the well is a Dry hole and now we Propose to P&A this well as follows:

- Plug 1 35 sx @ TD 12,929
 - Plug 2 35 sx @ 11420 to 12520' to cover the top of the Atoka at 12,470'
 - Plug 3 35 sx @ 8530 to 8580 to cover the top of the Abo @ 8580
 - Plug 4 50 sx @ 4927 to 5027' to cover the 9 5/8" casing shoe @ 4977
 - Plug 5 35 sx @ 2137 to 2237' to cover the 13 3/8" casing shoe @ 2187'
 - Plug 6 35 sx @ 300 to 400'
 - Plug 7 35 10' sx @ surface to cover 0 to 30' 100'
- TOP PENN @ 10900'*
GLOR 6400

After plugging a dry hole marker will be installed and the location reclaimed to NMOCD standards.

Spud Date: November 16, 2014 Rig Release Date: Rig still on location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature]
 TITLE President DATE 11/10/2014

Type or print name Phelps White E-mail address: pwiv@zianet.com PHONE: 575 626 7660

APPROVED BY: Maley Brown TITLE Dist Supervisor DATE 12/10/2014

Conditions of Approval (if any):

DEC 11 2014