

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-40615
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J R Phillips (302333)
8. Well Number 12
9. OGRID Number 873
10. Pool name or Wildcat Paddock

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ **DEC 12 2014**

2. Name of Operator
Apache Corp. **RECEIVED**

3. Address of Operator
P O box Drawer D Monument NM 88265

4. Well Location
Unit Letter B : 570 feet from the N line and 2240 feet from the E line
Section 1 Township 20S Range 36E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING P P&A NR T INT TO P&A P CSNG D TA OTHER: <input type="checkbox"/>	P&A R COMP CHG Loc RBDMS CHART OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: MPT for TA status <input type="checkbox"/>
--	--	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Perfs 5113' - 5389'

12/5/14 MIRU & POOH with rods & NU BOP.

12/8/14 POOH with tubing. Rig up wire line truck & set CIBP @ 5075' with 35' of cement on top. Load the casing with packer fluid.

12/9/14 Lay down the tubing & test the casing to 520 psi for 30 minutes with a loss of 30 lbs. Apache requests a TA status for this well.

This Approval of Temporary
Abandonment Expires 12/9/2019

C.O.A.-SUBMIT WELLBORE DIAGRAM

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE JD Ellison TITLE Instrument Tech DATE 12-8-14

Type or print name Jim Ellison E-mail address: JD.Ellison@apacheccorp.com PHONE: 441-7734

For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 12/15/2014

Conditions of Approval (if any):

DEC 17 2014

