Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR REAU OF LAND MANAGEMENT

⊙@D>Hobbss

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

If Indian, Allottee or Tribe Name

5. Lease Serial No.

NMNM63365

NOTICES AND REPORTS ON WELLS

Do not use	this	form	for p	roposals	to drill	or to	re-enter an
abandoned	well.	Use	Form	3160 - 3	(APD) fo	r sucl	n proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

7. If Unit or CA/Agreement, Name and/or No.

EWT & Tank Federal 1. Type of Well Öil Well 🛮 🗗 Gas Well□□ 8. Well Name and No. Tank 1 Federal #2 2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC API Well No. 3002530112 3a. Address 3b. Phone No. (include area code) PO BOX 1936 ~ ROSWELL NM 88202-1936 575.623.6601 10. Field and Pool, or Exploratory Area Young; Bone Spring North 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

11. County or Parish, State 330' FSL & 990' FWL, Sec. 1 SWSW, T18S, R32E -

Lea, New Mexico

12.	CHECK	APPROPRIATE	BOX(ES) TO	INDICATE	NATURE	OF NOTICE,	REPORT,	OR OTHER	DATA

TYPE OF SUBMISSION		TYI	PE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other Change Operator

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

This is a notification of Change of Operator on the above referenced well.

Harvey E. Yates Company, as new operator, accept all applicable terms, conditions, stipulations and restrictions concerning operatings conducted on this lease or portion of lease described.

BLM Bond No. NMB000317 Harvey E. Yates Company P.O. Box 1933 Roswell, NM 88202-1933

Change of Operator EFFECTIVE 9/1/2014

SEE ATTACHED FOR CONDITIONS OF APPROVAL

	Ö
	<u> </u>
14.	I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Tammy R. Link

Itle Production Tech

Signatur

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

2015 Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease BUTTAU OF LAND MAIN Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully-to-make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

620 E. Greene St Carlsbad, NM 88220 Ph: (575) 234-5972

Conditions of Approval for Change of Operator

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.