Submit 3 Copies To Appropriate District	Ct. A. CDI.	14			r	C 102	
Office	State of New Mexico			Form C-103			
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			June 19, 2008 WELL API NO.			
District II	OH CONCEDUATION DUMINON			27518			
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			ate Type of Le	ase		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			TATE 🗌	FEE 🛛		
District IV	Santa Fe, N	M 87505	6. State	Oil & Gas Lea	ise No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505							
	CES AND REPORTS ON W	ELLS	7. Leas	e Name or Unit	Agreement	Name	
(DO NOT USE THIS FORM FOR PROPO					-		
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	LATION FOR PERMIT" (FORM C-	TOT) FOR SUCH BBS C		18 State Com			
1. Type of Well: Oil Well	Gas Well  Other		1	Number #1	/		
2. Name of Operator		APR 0 2	201 9. OGR	ID Number	***************************************		
Matador Production Company		PAI 0"	228937				
3. Address of Operator	04-1500 D.II 777/7	5040 5040		I name or Wild			
One Lincoln Centre, 5400 LBJ Fre	eway, Ste 1500, Dallas, 1X /	5240-5240 RECE	/0840 A	ustin; Mississi	ppian		
4. Well Location							
Unit J: 1980' feet from the South						_	
Section 18	Township 14S	Range 36E		PM Lea	County		
• 1 • •	11. Elevation (Show whether	er DR, RKB, RT, GR,	etc.)				
12 Charle Annuariate Day	3969' GL	D 041-	D-4-				
12. Check Appropriate Box to	o indicate Nature of Noti	ice, Report or Oth	er Data				
NOTICE OF IN	TENTION TO:	l s	UBSFOUE	NT REPOR	RT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	• • • • • • • • • • • • • • • • • • • •			ERING CASI	ING □	
TEMPORARILY ABANDON	CHANGE PLANS	] COMMENCE	DRILLING OF	NS. P A	ND A		
PULL OR ALTER CASING	MULTIPLE COMPL	] CASING/CEN	MENT JOB				
DOWNHOLE COMMINGLE	0 -	سرماله ع					
OTHER: USTD 3 YR	s PendingReview?	CHAPI.					
OTHER: U1TD JYR  13. Describe proposed or comp	S (Clearly sta	OTHER:	s and give ner	tinent dates in	cluding estin	nated	
	ed work). SEE RULE 1103.						
completion or recompletion		or manapic compic	tions. Tituen	woncore diagre	an or propos	Cu	
1							
<ol> <li>See attached wellbore d</li> </ol>	iagram.						
a. Note: Arrowset	Packer @ 13,286', Top of C	pen Hole @ 13,31	5' (29')				
	%" tubing and 5 ½" casing	//). //	FLUTS				
3. Pressure up on casing to		. 7					
4. Hold pressure for 30 mir							
a. Use NMOCD app	proved recorder to monitor	r test.					
<ol><li>Provide test results to Re</li></ol>	oswell office. (Matador Pro	duction Company,	P.O. Box 193	6, Roswell, N	M 88202-19	936)	
See Attached Well Bore	Diagram	•	. 1141				
		C	ondition of A	Approval: no	otify		
		0	CD Hobbs	office 24 hor	urs		
Saud Data:	Dia Dala	ase Date:	or running	MIT Test &	Chart		
Spud Date: 9/26/1981	Rig Kele	ase Date.					
				<del></del>			
I hereby certify that the information	above is true and complete to	the best of my know	ledge and beli	ef			
Thereby, certify that the injoymation	( , 17	_	_				
SIGNATURE amy	June TITL	E Production	Hnalyst	DATE	3/30/2015		
			'				
Type or print name: Tammy R. Link	E-mail address: tlink@r	atadorresources.com	PHON	E: 575-623-660	01		
For State Use Only	X 1			1 1			
APPROVIDED A COLOR	WATRLE Dist.	SUDDIANA	DATE	4/1/71	215		
Conditions of Approval (if any):	The state of the s	- Lucian	<u></u>	-/5/50		0	
				APR	A 7 0	M.	
					U [ ]	Α,	

