

Submit 1 Copy To Appropriate District Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-34780
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1425-3
7. Lease Name or Unit Agreement Name Sombrero State
8. Well Number 1
9. OGRID Number 265378
10. Pool name or Wildcat <del>Kennitz</del> Lower Wolfcamp 98129
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator  
George A. Chase Jr., DBA: G and C Service

3. Address of Operator  
P. O. Box 1618 Artesia, NM 88211-1618

4. Well Location  
Unit Letter C : 1990 feet from the North line and 1980 feet from the West line  
Section 15 Township 16S Range 33E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☒

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well is currently completed in the Atoka 12,828-12,840'. G and C Service proposes to plug back to the wolfcamp formation.

1. Pull tubing and packer.
2. Set CIBP at 12,790'. Set 35' cement plug.
3. Set CIBP at 10,715'.
4. Set 35 foot plug immediately above CIBP.
5. Perforate wolfcamp formation @ 10,496- 10,580'.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gregory A. Chase TITLE Operating Administrator DATE 4/14/2015  
Type or print name Gregory A. Chase E-mail address: chevyco8@hotmail.com PHONE: (575) 703-6604  
For State Use Only  
APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 04/21/15  
Conditions of Approval (if any):

APR 22 2015

# Proposed Well Changes

Greg Chase  
API: 30-025-34780  
Sec. 15-16S-33E  
Lea County, NM

