Office	State of New Mexico	Form C-103		
District I Ene	ergy, Minerals and Natural Resources	June 19, 2008		
District II	IL CONSERVATION DIVISION	WELL API NO. 30-025-38840		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE X FEE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, INIVI 87303	6. State Oil & Gas Lease No. B0-1040-0011		
87505 SUNDRY NOTICES AND	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO D DIFFERENT RESERVOIR. USE "APPLICATION FO	DRILL OR TO DEEPEN OR PLOS SACK TO A	State 36		
PROPOSALS.) 1. Type of Well: ⊠Oil Well ☐ Gas Well	~ 31113	8. Well Number 001		
Name of Operator     Apache Corporation	AFI	9. OGRID Number 873		
3. Address of Operator	DECEIVED	10. Pool name or Wildcat		
303 Veterans Airpark Lane, Suite 1000 M	Midland, TX 79705	Bli O&G (Oil)/Tubb O&G/Brunson; DK-Abo S		
4. Well Location				
Unit Letter N : 640	feet from the South line and	1460 feet from the West line		
Section 36	Township 22S Range 37E	NMPM County Lea		
Section	evation (Show whether DR, RKB, RT, GR, e			
The Breath	3306' GL	(6.)		
NOTICE OF INTENTION  PERFORM REMEDIAL WORK □ PLUG A  TEMPORARILY ABANDON ☑ CHANG	AND ABANDON 🗌 REMEDIAL WO	JBSEQUENT REPORT OF: DRK		
<ul> <li>13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.</li> <li>Apache would like to temporarily abandon</li> <li>POOH &amp; LD rods &amp; tbg</li> <li>Set CIBP @ ~5475'</li> <li>Run MIT</li> <li>TA Well</li> </ul>	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions: this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h	notify nours		
<ul> <li>13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.</li> <li>Apache would like to temporarily abandon POOH &amp; LD rods &amp; tbg Set CIBP @ ~5475' Run MIT</li> </ul>	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions: this well, while evaluating its future use, pe	Attach wellbore diagram of proposed completion  r the following:  notify  ours		
<ul> <li>13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.</li> <li>Apache would like to temporarily abandon</li> <li>POOH &amp; LD rods &amp; tbg</li> <li>Set CIBP @ ~5475'</li> <li>Run MIT</li> <li>TA Well</li> </ul>	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions: this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h	Attach wellbore diagram of proposed completion r the following:  notify  cours  & Chart		
<ul> <li>13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.</li> <li>Apache would like to temporarily abandon POOH &amp; LD rods &amp; tbg Set CIBP @ ~5475' Run MIT TA Well</li> <li>A proposed WBD is attached.</li> </ul>	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions:  this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h  prior of running MIT Test  Rig Release Date: 07/17/2008	Attach wellbore diagram of proposed completion  r the following:  notify  a Chart		
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache would like to temporarily abandon POOH & LD rods & tbg Set CIBP @ ~5475' Run MIT TA Well  A proposed WBD is attached.  Spud Date: 05/06/2008	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions:  this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h  prior of running MIT Test  Rig Release Date: 07/17/2008	Attach wellbore diagram of proposed completion  r the following:  notify  a Chart		
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache would like to temporarily abandon POOH & LD rods & tbg Set CIBP @ ~5475' Run MIT TA Well  A proposed WBD is attached.  Spud Date: 05/06/2008	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions:  this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h  prior of running MIT Test  Rig Release Date: 07/17/2008	Attach wellbore diagram of proposed completion  r the following:  notify  Chart  dge and belief.		
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache would like to temporarily abandon POOH & LD rods & tbg Set CIBP @ ~5475' Run MIT TA Well  A proposed WBD is attached.  Spud Date: 05/06/2008  I hereby certify that the information above is the start of t	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions:  this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h  prior of running MIT Test  Rig Release Date: 07/17/2008  true and complete to the best of my knowle	Attach wellbore diagram of proposed completion  r the following:  notify  calcalate the control of the control		
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache would like to temporarily abandon POOH & LD rods & tbg Set CIBP @ ~5475' Run MIT TA Well  A proposed WBD is attached.  Spud Date: 05/06/2008  I hereby certify that the information above is the start of t	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions:  this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h  prior of running MIT Test  Rig Release Date: 07/17/2008	Attach wellbore diagram of proposed completion  r the following:  notify  calcalate the control of the control		
13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache would like to temporarily abandon POOH & LD rods & tbg Set CIBP @ ~5475' Run MIT TA Well  A proposed WBD is attached.  Spud Date: 05/06/2008  I hereby certify that the information above is the start of t	rations. (Clearly state all pertinent details, E RULE 1103. For Multiple Completions:  this well, while evaluating its future use, pe  Condition of Approval:  OCD Hobbs office 24 h  prior of running MIT Test  Rig Release Date: 07/17/2008  true and complete to the best of my knowle	Attach wellbore diagram of proposed completion  r the following:  notify  calcalate the control of the control		

APR 2 8 2015

de

Apache Corporation					
Co. Rep Well Name	State 36	 Well No. 1			
Field County	Lea				
State	New Mexico				
Date	4/22/2015	<del></del>			
GL	3,306'				
KB corr	11'				

Casing	O.D.	Grade	₩t	Depth	TOC
Surf	8-5/8"	K-55	24#	1,254'	Surf
Inter					
Prod	5-1/2"	K-55 & L-80	17#	8,000'	Surf
Liner					

**Description**DV tool

CIBP w/3 sx cmt cap

