

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
"Preserving the Integrity of Our Environment"

19-May-15

SAHARA OPERATING CO  
P.O. BOX 4130  
MIDLAND TX 79704

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

***INSPECTION DETAIL SECTION***

NORTH EL MAR UNIT No.062				H-36-26S-32E	30-025-25422-00-00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By: Inspection No.
05/19/2015	Routine/Periodic	Mark Whitaker	Yes	No	8/22/2015 iMAW1513934701
<b>Violations</b> Surface Damage/Restoration					
<b>Comments on Inspection:</b> Rule 19.15.25.10 requires operator restore location no later than one year after completion of plugging operations. NEED TO REMOVE SEVERAL WELLHEADS, PIECES OF CASING, WELL SIGN, SUCKER ROD FENCING, STUB POLES, AND INJECTION RISER NEXT TO P&A MARKER. INJECTION RISER SHOULD BE DISCONNECTED AT INJECTION HEADER, FLUSHED, AND CUT OFF 2' BELOW GROUND LEVEL AT THE MARKER.					

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.


Sincerely,

  
Compliance Officer

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



015H14150977  
**\$0.48**  
05/19/15  
Mailed From 88240

HASLER

US POSTAGE

SAHARA OPERATING CO  
PO BOX 4130  
MIDLAND, TX 79704-4130