

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
 EnerVest Operating, LLC

3. Address of Operator
 1001 Fannin St., Suite 800 Houston, TX 77002-6707

4. Well Location
 Unit Letter : A 660 Feet from the North Line and 660 Feet from the East Line
 Section 8 Township 21S Range 36E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3578' GR

WELL API NO.
 30-025-04567

5. Indicate Type of Lease
 STATE FEE

6. State Oil & Gas Lease No.
 A-1350

7. Lease Name or Unit Agreement Name
 State A Com

8. Well Number
 004

9. OGRID Number
 143199

10. Pool name or Wildcat
 Eumont (Yates/7 Rivers/Queen) (Gas)

HOBBS OGD
 JUN 25 2015
 RECEIVED

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING <SWD INJECTION>
 CONVERSION RBDMS
 RETURN TO TA
 CSNG CHG LOC
 INT TO PA P&A NR P&A R

SUBSEQUENT REPORT OF:
 REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER: Temporarily Abandon

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

June 9, 2015: MIRU Pulling Unit. ND Production Equipment. POOH all rods and pump. NDWH, NUBOP. POOH w/tbg. RUWL. Set 7" CIPB @ 3345'. Dump bail 40' cement on top of plug. SWI. SDON.

June 10, 2015: RIH and set 7" CIBP @ 2860'. Cap w/40' cement. Load casing w/2% KCL. Pressure test @ 600 psi for 30 minutes. Good test. RDMO Pulling Unit.

June 22, 2015: MIT witnessed and signed by Maxey Brown, NMOCD. (Chart attached)
GEORGE BOWER

This Approval of Temporary Abandonment Expires 6/22/2018

Spud Date:

Rig Release Date: C.O.A

PROVIDE CURRENT WELLBORE DIAGRAM


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shelly Doescher TITLE Agent DATE 06/26/2015
 Type or print name Shelly Doescher E-mail address: sdoescher@enervest.net Phone: 505-320-5682

For State Use Only
 APPROVED BY: Maxey Brown TITLE Dist Supervisor DATE 6/25/2015
 Conditions of Approval (if any)

JUN 29 2015

h
 MB



HOBBS OCD
JUN 25 2015
RECEIVED

[Handwritten signature]