Submit I Copy To Appropriate District Office	State of New Mexico			Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources			Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-025-25616	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lea	Se
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra	ncis Dr.	STATE	FEE 🗍
District IV – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Leas	
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	<u> </u>	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PL	UG BACK-TOPACD	Blinebry-Drinkard-S	
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) F	UB GUIGHTO -	1	
J. Type of Well: Oil Well	Gas Well  Other SWD Well	o # 2015	8. Well Number N-18	
2. Name of Operator	JUL 2		9. OGRID Number	
Rice Operating Company				
3. Address of Operator	RECZIVED		10. Pool name or Wildcat	
122 West Taylor		" SW)	San Andres	
4. Well Location	1150/3			
	et from the South line and 2250 feet			
Section 18	Township 22S	Range 37E	NMPM Le	a County
	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.)		
	3419' GL; 3424' KB			e un servicio de la companya dela companya dela companya de la companya de la companya de la companya dela companya de la comp
12 (1 1		T. CNI.	D ( Od D (	•
12. Check	Appropriate Box to Indicate N	lature of Notice,	Report or Other Data	
NOTICE OF IN	NTENTION TO:	SUBS	SEQUENT REPOR	T OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		RING CASING
TEMPORARILY ABANDON 🔲	CHANGE PLANS ☐	☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗍	
DOWNHOLE COMMINGLE				·
CLOSED-LOOP SYSTEM  OTHER:		OTHER: MIT with	Chart	K⊠
OTHER.		OTHER. WIT WILL	Chart	
13. Describe proposed or comp	pleted operations. (Clearly state all	pertinent details, and	give pertinent dates, incl	uding estimated date
	ork). SEE RULE 19.15.7.14 NMAG	C. For Multiple Con	npletions: Attach wellbor	e diagram of
proposed completion or rec	completion.			
	·			
Ran MIT with Chart Witnessed by George Bower on July 20, 2015				
				i
Smud Datas	Rig Release Da	ata:		
Spud Date:	Kig Kelease Da	ate.		
I hereby certify that the information	above is true and complete to the h	est of my knowledge	and belief	· · · · · · · · · · · · · · · · · · ·
Thereby certify that the information	above is true and complete to the or	est of my knowledge	and belief.	
1 //				
SIGNATURE	TITLE Opera	ations Manager DA	TE July 22, 2015	<del></del>
		DUONE, 676	202 0174	
Type or print name Jon Rampone	:-mail address: <u>jrampone@riceswd</u>	.com PHONE: 3/3	-373-7174	
For State Use Only				
R	,	21000	_	Y/n /
APPROVED BY: Bill Somamake TITLE Staff Manager DATE 8/20/2015				
Conditions of Approval (if any):			AUG 28 20	15
		•	AUG & O LU	¥10