Submit 1 Copy 7 Office	To Appropriate District		ew Mexico			Form C-103			
District I - (575)	District I – (575) 393-6161 Energy, Minerals and Natural Resou				Revised July 18, 2013 WELL API NO.				
District II – (575	Dr., Hobbs, NM 88240 5) 748-1283	OU CONCEDU		20.025		/			
811 S. First St., . District III – (50	Artesia, NM 88210	OIL CONSERVA	St. Francis Dr.	5. Indic	ate Type of Lease				
1000 Rio Brazos	Rd., Aztec, NM 87410					TEE			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM					Oil & Gas Lease 1	No.			
87505				35602	NT				
(DO NOT USE		ES AND REPORTS ON LS TO DRILL OR TO DEEPE			e Name or Unit Ag	reement Name			
DIFFERENT RE		TION FOR PERMIT" (FORM	C-101) FOR SUCH	Gen. M	ontcalm 25 State	/			
PROPOSALS.)	Vell: Oil Well 🛛 G	as Well 🔲 Other	HOBBS OCT	8. Well	Number	1 /			
2. Name of C		/	_	9. OGR	ID Number 2:	56512			
CML Explora			<u></u>	5	1				
3. Address o	-	x 890 TX 79549	ц		I name or Wildcat K; PENN & CORBIN; '	WOLFCAMP. EAST			
4. Well Loca	• •		A/ RECEIVED		, ,	,			
	Letter H : 1	980 feet from the			from the East	line			
Sect		Township 17-S							
		11. Elevation (Show when							
		4088' GR							
	12. Check Ap	propriate Box to Indi	icate Nature of N	otice, Report o	or Other Data				
	NOTICE OF INT	ENTION TO:		E-PERMITTIN		INJECTION>			
				CONVERSION	I RBI	Бмs			
				RETURN TO	TA_				
		MULTIPLE COMPL				HG LOC			
CLOSED-LO			l II	NT TO PATTA	P&A NR	P&A R			
OTHER:			OTHER:			·····			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of									
	used completion or recon		+ NIVIAC. FOI MUIL	ipie Completions.	Attach wendore t	nagram of			
	•	•							
		25'. LD 1 jt, RU cementer							
		/8" gun (2spf) and squees				WOC ? Tag			
		olug @ (9,860'- 10,060') olug @ (4660'- 5100'), W		22200 6	2820				
•									
5. Cut & Pull \pm 4400' of 7" casing 6. Spot 65 sx class "C" cement plug @ (4250'-4450') $-$ 5for 45 5x5 @ 2600'									
5. Cut & Pull $\pm 4400'$ of 7" casing 6. Spot 65 sx class "C" cement plug @ (4250'-4450') 7. Spot 65 sx class "C" cement plug @ (300'-500') $= 500T 4555x5 @ 1500'$									
8. Spot 2	25 sx class "C" cement p	olug @ (3'-60')	- WOC \$ TAG	-					
9. RDMOPU. Cut off well head, weld on cap and dry hole marker. Remove anchors, trash and flowline. Clean pit. Haul off caliche									
from	location and road. Repla	ce with top soil.				• •			
		× ×		Th	e Oil Conserva	tion Division			
Г	C/14/2006		0/28		ST BE NOTIF				
Spud Date:	6/14/2006	Rig Re	lease Date: 9/28/						
L			L	Prior	to the beginnin	g of operations			
I horoby cortifi	w that the information ab	ove is true and complete	to the best of my kn	owledge and beli	əf				
T nereby certify	y that the impormation ab	ove is true and complete	, v the best of my kn	owledge and bein	-1.	; ,			
,	(2			a	luit -			
SIGNATURE DATE TITLE ENGINEER DATE 9/14/2015									
Type or print n	name Jordan Owens	F-mail	address: owensj@	cmlexp.com	PHONE: 32	1 5-573-0750			
For State Use Only									
APPROVED BY:									

SEP	I	8	2015
-----	---	---	------

1

ì

UL.

CML EXPLORATION, LLC

PROPOSED P&A WELLBORE DIAGRAM

