Sul mit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240 District II OH CONSERNATION DIVISION	WELL API NO. 30-025- 11017
1301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505	STATE   FEE   STATE
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 8910138170 -
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Myers Langlie Mattix Unit
1. Type of Well: Oil Well Gas Well Other Injection	8. Well Number
2. Name of Operator	9. OGRID Number
OXY USA WTP Limited Partnership	192463
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710-0250	Langlie Mattix 7Rvr Qn-GB
4. Well Location	
Unit Letter G: 1966 feet from the North line and 1980 feet from the east line	
Section 5 Township 245 Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	n Material
12. Check Appropriate Box to Indicate Nature of Notice,  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  Abandonment Expires COTHER: CIT - TA	SEQUENT REPORT OF:  ALTERING CASING  NG OPNS. PLUG AND ABANDONMENT
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
OXY USA WTP LP requests to temporarily abandon this well for possible future use.	
TD- 3687 PBTD- 3560 Perfs- 34(0-354)	Pkr <del>/CIBP</del> 3311
1. Notify BLM/NMOCD of casing integrity test 24hrs in advance. 2. RU pump truck <u>volv(os</u> , circulate well with treated water, pressure test casing to <u>see</u> # for 30 min.  Abandonment Expires	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE TITLE Sr. Regulatory Analyst DATE 11/14/05	
Type or print name David Stewart  E-mail address:  Telephone No. 432-685-5717	
APPROVED BY Conditions of Approval, if any:	NOV 1 7 2005

