Office Energy, Minerals and Natural Resources	Form C-103
	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025- 25681
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE 🖫 FEE 🗌
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 8910138170 - B 1327
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Myers Langlie Mattix Unit
1. Type of Well:	8. Well Number
Oil Well Gas Well Other Injection	ut
2. Name of Operator	9. OGRID Number
OXY USA WTP Limited Partnership	192463
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710-0250	Langlie Mattix 7Rvr On-GB
4. Well Location	
Unit Letter O : 660 feet from the South line and	2080 feet from the east line
Section 32 Township 235 Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, e	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Di	stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construct	
12. Check Appropriate Box to Indicate Nature of Notice	Report, or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	
	ARANDONMENT
PULL OR ALTER CASING	ABANDONMENT
PULL OR ALTER CASING	
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give	Status X e pertinent dates, including estimated date
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactional Actactions of the complete of the completion of the completi	Status X e pertinent dates, including estimated date
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.	Status X re pertinent dates, including estimated date in wellbore diagram of proposed completion
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well	Status X re pertinent dates, including estimated date in wellbore diagram of proposed completion
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.	Status X re pertinent dates, including estimated date in wellbore diagram of proposed completion
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3709 Perfs-3355-355	Status X The pertinent dates, including estimated date in wellbore diagram of proposed completion in the proposed for possible future use. Pkr/CIBP3337
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well TD- 3727 PBTD- 3709 Perfs- 3335-365	Status Experiment dates, including estimated date in wellbore diagram of proposed completion for possible future use. Pkr/CIBP3337
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3702 Perfs-3335-365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck Lolyon, circulate well with treated to 589 # for 30 min	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion for possible future use. Pkr/CIBP
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3702 Perfs-3335-365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck Lolyon, circulate well with treated to 589 # for 30 min	Status Experiment dates, including estimated date in wellbore diagram of proposed completion for possible future use. Pkr/CIBP3337
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3702 Perfs-3355-365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck 101405, circulate well with treated to 585 # for 30 min. Aba	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion For possible future use. Pkr/CIBP3337 Trance. Water pressure test Gasing and
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3709 Perfs-3355-355 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck Loldon, circulate well with treated to 580 # for 30 min. Abarance of the proposed or complete to the best of my knowledge of the proposed or complete to the best of my knowledge of the proposed or complete to the best of my knowledge of the proposed or complete to the best of my knowledge of the proposed or complete to the best of my knowledge of the proposed or complete to the best of my knowledge or complete to the proposed or complete to the p	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion For possible future use. Pkr/CIBP3337 Trance. Water pressure test casing indonment Expires Endonment Expires The and belief. I further certify that any pit or below.
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD- 3727 PBTD- 3709 Perfs- 3355 - 365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck 10105, circulate well with treated to 580 # for 30 min. Abarana Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed opclosed according to NMOCD guidelines , a general permit	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion for possible future use. Pkr/CIBP
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3709 Perfs-3355-365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck to 10105, circulate well with treated to 580 # for 30 min. Aba I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Regula	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion For possible future use. Pkr/CIBP3337 Trance. Water pressure test casing indonment Expires Endonment Expires The and belief. I further certify that any pit or below.
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD- 3727 PBTD- 3709 Perfs- 3355 - 365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck 10105, circulate well with treated to 580 # for 30 min. Abarana Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed opclosed according to NMOCD guidelines , a general permit	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion For possible future use. Pkr/CIBP
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3702 Perfs-3335-3455 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck 10405, circulate well with treated to 585 # for 30 min. Abanda Thereby certify that the information above is true and complete to the best of my knowledged grade tank has been/will be constructed acclosed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Regulation E-mail address:	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion for possible future use. Pkr/CIBP
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3702 Perfs-3355-365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck to 10405, circulate well with treated to 580 # for 30 min. Aba I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Requise E-mail address: Type or print name David Stewart For State Use Only	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion For possible future use. Pkr/CIBP3337 Tance. The provided of the proposed completion The pr
OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3727 PBTD-3702 Perfs-3355-365 1. Notify BLM/NMOCD of casing integrity test 24hrs in add 2. RU pump truck to 10405, circulate well with treated to 580 # for 30 min. Aba I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Requise E-mail address: Type or print name David Stewart For State Use Only	Status The pertinent dates, including estimated date in wellbore diagram of proposed completion for possible future use. Pkr/CIBP

