Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-06366
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOSA	ES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Northeast Drinkard Unit
PROPOSALS.) 1. Type of Well: Oil Well (X)	, · · · · · · · · · · · · · · · · · · ·	8. Well Number 320
2. Name of Operator		9. OGRID Number
Apache Corpo	ration	00873
3. Address of Operator 6120 South Tulsa, OK	Yale, Suite 1500 74136-4224	10. Pool name or Wildcat Eunice; Blinebry - Tubb - Drinkard - North
4. Well Location		Lunice, Difficulty - Tubb - Difficulty - North
Unit Letter W : 6	60 feet from the South line and	1780 feet from the West line
Section 2	Township 21S Range 37E	NMPM CountyLea
	11. Elevation (Show whether DR, RKB, RT, GR,	
Pit or Below-grade Tank Application _ or	3476' GR	
Pit type Depth to Groundwat		Distance from nearest surface water
Pit Liner Thickness: mil		Construction Material
	ppropriate Box to Indicate Nature of Noti	*
NOTICE OF INT		UBSEQUENT REPORT OF:
TEMPORARILY ABANDON	<u>=</u>	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEN	
OTHER:	OTHER:Repa	air Wellhead and Test
13. Describe proposed or comple	OTHER:Repa	-
13. Describe proposed or comple of starting any proposed wor or recompletion.	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or comple of starting any proposed wor or recompletion.	OTHER:Repa	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed work or recompletion.11/2/2005 Repair leak in wellhead proposed in the starting any proposed work or recompletion.	OTHER:Repa	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion.11/2/2005 Repair leak in wellhead proposed that attached: Test Date 11/2/2005	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead pure the completed of the complete of the	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead proposed that attached: Test Date 11/2/2005 Pressure Reading: 	OTHER:Repa	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure the complete of the co	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead pure the completed of the complete of the	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure the complete of the co	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead pure the completed of the complete of the	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead pure the completed of the complete of the	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead pure the completed of the complete of the	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work or recompletion. 11/2/2005 Repair leak in wellhead pure the completed of the complete of the	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure the complete of the co	OTHER:Repa	s, and give pertinent dates, including estimated date. Attach wellbore diagram of proposed completion or 30 mins okay. Put on injection.
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure Chart attached: Test Date 11/2/2005 Pressure Reading: Length of Time: Test Witnessed: I hereby certify that the information a	OTHER:Repa teted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions ackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins no	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure Chart attached: Test Date 11/2/2005 Pressure Reading: Length of Time: Test Witnessed: I hereby certify that the information a	OTHER:Repa teted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions ackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins no	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion or 30 mins okay. Put on injection. ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure Chart attached: Test Date 11/2/2005 Pressure Reading: Length of Time: Test Witnessed: I hereby certify that the information algrade tank has been/will be constructed or classification.	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins no	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion or 30 mins okay. Put on injection. ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan nician DATE 11/18/2005
13. Describe proposed or complete of starting any proposed wor or recompletion. 11/2/2005 Repair leak in wellhead pure Chart attached: Test Date 11/2/2005 Pressure Reading: Length of Time: Test Witnessed: I hereby certify that the information alignade tank has been/will be constructed or classification.	OTHER:Reparted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions eackoff, repack seal assembly. Retest to 500 psi for by Vista Services 520 psi 30 mins no	ir Wellhead and Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion or 30 mins okay. Put on injection. ledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan

APPROVED BY: Law Conditions of Approval (if any):

TITLE 2 2 2005

