Conditions of Approval, if any

Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-37445 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE | FEE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH North Hobbs G/SA Unit PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other 733 2. Name of Operator 9. OGRID Number Occidental Permian Limited Partnership 157984 3. Address of Operator 10. Pool name or Wildcat P.O. Box 4294, Houston, TX 77210-4294 Hobbs: Grayburg - San Andres 4. Well Location South 1080 SHL: Unit Letter feet from the line and feet from the line 1790 BHL: East South Section 19 Township 18-S Range 38-E **NMPM** County 11. Elevation (Show whether DR. RKB, RT. GR. etc.) 3655' GR Pit or Below-grade Tank Application or Closure Pit type \_\_\_\_\_ Depth to Groundwater Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_ Pit Liner Thickness: Below-Grade Tank: Volume\_ bbls; Construction Material . 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING MULTIPLE CASING TEST AND** COMPLETION **CEMENT JOB** OTHER: OTHER: Run 5-1/2" Production Casing X 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. See Attachment I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines X , a general permit or an (attached) alternative OCD-approved plan TITLE Regulatory Compliance Analyst DATE 11/17/05 SIGNATURE\_ E-mail address: Mark Stephens@oxy.com Mark Stephens Type or print name Telephone No. (713) 366-5158 For State Use Only APPROVED BY

DATE

NOV 2 2 2005

11/13/05 -

11/14/05: Drill to TD at 4520'. RU casing crew and run 105 jts. 5-1/2", 15.5#, J-55, LT&C casing with 10 centralizers and set at 4520'. RU Halliburton and cement first stage with 250 sx. Premium Plus. Drop bomb, open DV tool, and circulate 60 sx. to surface. Circulate well for 4 hours. Cement second stage with 450 sx. Class 'C' (lead) and 100 sx. Premium Plus (tail). Circulate 192 sx. to surface off second stage. ND BOP and set casing slips. Cut off casing and NU tubing spool. Jet and clean pits and RD.

Release drilling rig at 8:00 p.m., 11/14/05.