هر ال	
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION	30-025-11164
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Thomas A
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 2
2. Name of Operator	9. OGRID Number
OXY USA WTP Limited Partnership	192463
3. Address of Operator P.O. Box 50250 Midland. TX 79710-0250	10. Pool name or Wildcat Jalmat Tansill-Yates-7Ryrs
4. Well Location	
Unit Letter <u>G</u> : 2310 feet from the north line and	2210 feet from the east line
Section 19 Township 24S Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR,	etc.)
Pit or Below-grade Tank Application     or Closure	
Pit type <u>Steel</u> Depth to Groundwater <u>150</u> Distance from nearest fresh water well <u>N/A</u>	Distance from nearest surface water N/A
Pit Liner Thickness:       N/A mil       Below-Grade Tank: Volumebbls; Construct         12. Check Appropriate Box to Indicate Nature of Notice	ce, Report, or Other Data
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume       bbls; Construction         12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO:       Nature of Notice SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON I       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL	ce, Report, or Other Data JBSEQUENT REPORT OF: K
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume       bbls; Construction         12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO:       Nature of Notice SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON IX       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB	ce, Report, or Other Data JBSEQUENT REPORT OF: K
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume       bbls; Construction         12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO:       Nature of Notice SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE       CASING TEST AN	ce, Report, or Other Data JBSEQUENT REPORT OF: K
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume       bbls; Construction         12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       Nature of Notice         PERFORM REMEDIAL WORK       PLUG AND ABANDON       SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.	ce, Report, or Other Data JBSEQUENT REPORT OF: K
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume      bbls; Construction         12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO:       SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       TD-3680'       PBTD-3487'       OH-2870-3487'         8-5/8"       24# csg @ 1204' w/625sx, 11" hole, TOC-Su 5-1/2"       14# csg @ 2870' w/250sx, 7-7/8" hole, TOC 1. RIH & Set CIBP @ 2820', Dump 5sx cmt to 278 2. Perf @ 1254', sqz 45sx cmt to 1154'       T         3. Perf @ 300', sqz 45sx cmt to 200'-WOC-Tage 4. 10sx cmt Surface Plug       Astrona and the set of the state to the state	ce, Report, or Other Data JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT Is pretinent dates, including estimated date ach wellbore diagram of proposed completion ALTERING CASING ABANDONMENT Is pretinent dates, including estimated date ach wellbore diagram of proposed completion ALTERING CASING ABANDONMENT Is pretinent dates, including estimated date ach wellbore diagram of proposed completion ALTERING CASING ABANDONMENT
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume      bbls; Construct         12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       Nature of Notic         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       TD-3680'       PBTD-3487'       OH-2870-3487'         8-5/8"       24# csg @ 1204'       w/625sx, 11" hole, TOC-Su 5-1/2"       14# csg @ 2820', w/250sx, 7-7/8" hole, TOC 1. RIH & Set CIBP @ 2820', Dump 5sx cmt to 278 2. Perf @ 1254', sqz 45sx cmt to 1154'       7         3. Perf @ 1254', sqz 45sx cmt to 200'-WOC-Tag 4. 10sx cmt Surface Plug 10# MLF between plugs       B         Thereby certify that the information above is true and complete to the best of my knowled       B	ce, Report, or Other Data JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING AL
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume      bbls; Construct         12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       Nature of Notice SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON [X]       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       The 3680' PBTD-3487' OH-2870-3487' 8-5/8" 24# csg @ 1204' w/625sx, 11" hole, T0C-Su 5-1/2" 14# csg @ 2870' w/250sx, 7-7/8" hole, T0C 1. RIH & Set CIBP @ 2820', Dump 5sx cmt to 278 2. Perf @ 1254', sqz 45sx cmt to 1154' 3. Perf @ 300', sqz 45sx cmt to 200' WOC-Tach 4. 10sx cmt Surface Plug 10# MLF between plugs       B         Thereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines - , a general perm	ce, Report, or Other Data UBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING A
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume      bbls; Construct         12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON       SU       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       OT-3680' PBTD-3487'         18. 55/8" 24# csg @ 1204' w/625sx, 11" hole, TOC-Su 5-1/2" 14# csg @ 2870' w/250sx, 7-7/8" hole, TOC 1. RIH & Set CIBP @ 2820', Dump 5sx cmt to 278 2. Perf @ 1254', sqz 45sx cmt to 1154'	ce, Report, or Other Data JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT add give pertinent dates, including estimated date ach wellbore diagram of proposed completion arf-Circ -1282'-Calc AG IE OIL CONSERVATION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISIO
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume       bbls; Construct         12. Check Appropriate Box to Indicate Nature of Notic         NOTICE OF INTENTION TO:       SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON       SU         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       TD-3680'       P\$TD-3487'       OH-2870-3487'         8-5/8" 24# csg @ 1204'       w/625sx, 11" hole, TOC-Su 5-1/2" 14# csg @ 2870'       w/250sx, 7-7/8" hole. TOC 1. RIH & Set CIBP @ 2820', Dump 5sx cmt to 278         2. Perf @ 1254', sgz 45sx cmt to 1154'       T       J         3. Perf @ 300', sgz 45sx cmt to 200'-WOC-Ta 4. 10sx cmt Surface Plug 10# MLF between plugs       B         Thereby certify that the information above is true and complete to the best of my know/kC grade tank has been/will be constructed ar closed according to NMOCD guidelines, a general perm SIGNATURE       TITLESr Regu         UP or print name David Stewart       TITLESr Regu	ce, Report, or Other Data JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT add give pertinent dates, including estimated date ach wellbore diagram of proposed completion arf-Circ -1282'-Calc AG IE OIL CONSERVATION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISION DIVISION MUSE IE OIL CONSERVATION DIVISION DIVISIO
Pit Liner Thickness:       N/A       mil       Below-Grade Tank: Volume      bbls; Construct         12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:       SU         PERFORM REMEDIAL WORK       PLUG AND ABANDON       SU       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AN CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.       OTHER:         13. Describe proposed work).       SEE RULE 1103. For Multiple Completions: Atta or recompletion.       Th-3680' PBTD-3487' OH-2870-3487' 8-5/8" 24# csg @ 220', Ump 5sx cmt to 278 2. Perf @ 1254', sqz 45sx cmt to 1154'	ce, Report, or Other Data JBSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. PLUG AND ABANDONMENT ABANDONMENT D give pertinent dates, including estimated date ach wellbore diagram of proposed completion AGA give pertinent dates, including estimated date ach wellbore diagram of proposed completion ABANDONMENT D give pertinent dates, including estimated date ach wellbore diagram of proposed completion ABANDONMENT D GIVE PERTURBATION DIVISION MUT FOIL CONSERVATION DIVISION MUT E NOTIFIED 24 HOURS PRIOR TO THE GIVENTIAL OF PLUGOING OPERATION and beller. Further certify the any proposed plan and atory Analyst DATE ALLOS

-

## C OXY USA WTP LP Thomas A #2 API No. 30-025-11164

j#

