

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

|                                                                                                                     |
|---------------------------------------------------------------------------------------------------------------------|
| WELL API NO.<br><b>30.025.29962</b>                                                                                 |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>                 |
| 6. State Oil & Gas Lease No.                                                                                        |
| 7. Lease Name or Unit Agreement Name:<br><b>Anderson</b>                                                            |
| 8. Well No.<br><b>101</b>                                                                                           |
| 9. Pool Name or Wildcat<br><b>SWD</b><br><b>Abandonment San Andres</b><br><b>&lt; 96127 &gt;</b><br><b>Glorieta</b> |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.)<br><b>3539</b>                                                   |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other **SWD**

2. Name of Operator

**Smith & Marrs, Inc.**

3. Address of Operator

**601 W. Illinois, Hobbs NM 88242**

4. Well Location

Unit Letter **0** : **330** feet from the **South** line and **1980** feet from the **East** line

Section **8** Township **20** Range **37** NMPM **E** County **Lea**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: **Convert to SWD** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. **OCD R-12375 \* will start as soon as unit available**

1. Move in pulling unit, and remove production equipment
2. Run in hole with tubing, set CIBP at 5300' with 5x cement on top.
3. Pressure test casing, circulate hole clean.
4. Run in hole and perforates from 4350 to 5280.
5. Acidize perforations
6. Run in hole with 3 1/2 inch plastic lined tubing + packer and set at 4250'
7. Pressure test casing above packer + run chart.
8. Load backside with packer fluid.
9. Put on injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **Eddie W. Seay** TITLE **Agent** DATE **11/28/05**

Type or print name **Eddie W. Seay** Telephone No. **505-392-2236**  
(This space for State use)

APPROVED BY **Gary W. Wink** TITLE **OC FIELD REPRESENTATIVE W/STAFF MANAGER** DATE **NOV 29 2005**  
Conditions of approval, if any