Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals	and Natural Resources	WELL API N	May 27, 2004 NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5 7 11 4 7	30-025-28649 2924	
District III	1220 South St. Francis Dr.		5. Indicate T	ype of Lease E X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Nar Cockburn B	7. Lease Name or Unit Agreement Name Cockburn B State	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other				8. Well Number 7	
2. Name of Operator Latigo Petroleum, Inc.			9. OGRID N	9. OGRID Number 227001	
3. Address of Operator 550 W. Texas, Suite 700				10. Pool name or Wildcat	
Midland, 1X /9/01			E K Yates S	E K Yates Seven Rivers Queen	
4. Well Location Unit Letter G: 1610 feet from the N line and 2050 feet from the E line					
Unit Letter G : Section 1		S Range 33E	NMPM	et from the E line CountyLea	
Section 1		hether DR, RKB, RT, GR, e		CountyLea	
Pit or Below-grade Tank Application 🔲 o	4101.8' GR				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil			Construction Mater		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A					
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMI	ENT JOB		
OTHER:		☐ OTHER:		Service of the servic	
	leted operations. (Clearl		and give pertinen	t dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
RIH to CIBP @ 4016', spot 10 sx cmt.					
Circulate hole w/ 9.5# mud laden fluid 3409 - 3389'. POH to 3489', spot 25 sx cmt plug 2988 - 2888'.					
POH to 2988', spot 25 sx cmt plug.					
Cut & pull csg @ 2400'.			,	63742529	
Spot 35 sx cmt plug 2450 - 2350'. Spot 35 sx cmt plug 1455 - 1355'.			12		
Spot 35 sx cmt plug 416 - 316'.			/S ^V		
Spot 10 sx surface plug. Cut off wellhead & anchors, install dry hole marker & clean location.					
Cut off weithead & alichors, histan	dry note marker & clean	location.	50501 18 10 20 20 2	Control of the	
		U DOMOIONI RAHIST	19	P God M GO	
THE OIL CHINSERVATION DIVISION 1880 1880 1880 1880 1880 1880 1880 188					
BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.					
BEGIN	NING OF PLUGGI	MG OPERATIONS.	*		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-					
grade tank has been/will be constructed or closed according to NMOCD guidelines ., a general permit or an (attached) alternative OCD-approved plan .					
SIGNATURE LAG H	unt	TITLE Regulatory Analyst		DATE 12/02/2005	
Type or print name Lisa Hunt		E-mail address: lhunt@lat	igopetro.com	Telephone No. (432)684-4293	
For State Use Only	1 1 el	TITLE	TW FEE BY	חבס -	
APPROVED BY: Conditions of Approval (if any):	J. Wink	TITLE	HYE HISTAFF M	ANACDATE 0 6 2005	