
Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Re	esources May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-33428
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIV	1510N 5 Indicate Type of Lease
District III 1220 South St. Francis I 1000 Rio Brazos Rd., Aztec, NM 87410	Or. STATE STEE
District IV Santa Fe, NWI 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-1306
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BADIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC	Tuotam Stories (Soc21)
PROPOSALS.)	8. Well Number 132
1. Type of Well: Oil Well Gas Well Other Temporarily Aband 2. Name of Operator	9. OGRID Number
Chevron U.S.A. Inc. (4323)	4323
3. Address of Operator	10. Pool name or Wildcat
15 Smith Road	Vacuum; Glorieta (62160)
Midland, Texas 79705 4. Well Location	
	line and 890 feet from the East line
	2 35-E NMPM County LEA
11. Elevation (Show whether DR, RKB)	
3974' GR	
Pit or Below-grade Tank Application or Closure NA, propose to use Steel Tanks w/B	
Pit type Depth to Groundwater Distance from nearest fresh water w	ell Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material
12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REM	MEDIAL WORK ☐ ALTERING CASING ☐
	MMENCE DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING MULTIPLE COMPL CAS	SING/CEMENT JOB
	-
OTHER: Propose . DTH	HER: Continue Temporary Abandon Status w/MIT Chart
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Control of Starting and Proposed Work).	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all perting	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date
OTHER: Propose OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformation or recompletion.	HER: Continue Temporary Abandon Status w/MIT Chart cent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion
OTHER: Propose OTHER: Propose OTHER: Propose OTHER: Describe proposed or completed operations. (Clearly state all perting of starting any proposed work). SEE RULE 1103. For Multiple Conformation recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attacher	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron
OTHER: Propose OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformation or recompletion.	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformer recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations.	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformation recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron endoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformation recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron endoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertino of starting any proposed work). SEE RULE 1103. For Multiple Conformation recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron endoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformation recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date empletions: Attach wellbore diagram of proposed completion d integrity test-chart performed on 11/11/2005, Chevron endoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all perting of starting any proposed work). SEE RULE 1103. For Multiple Conformation or recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attached U.S.A. Inc. respectfully requests approval to retain the Temporarily Abasecondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# Abandonment E	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conformation recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500'	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future expires expires my knowledge and belief. I further certify that any pit or below-
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all perting of starting any proposed work). SEE RULE 1103. For Multiple Conformation or recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attached U.S.A. Inc. respectfully requests approval to retain the Temporarily Abasecondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# This Approval Of Abandonment Elements of the best of grade tank has been/will be constructed or closed according to NMOCD guidelines \(\D \), a get	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future expires expires expires. Temporary expires e
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all perting of starting any proposed work). SEE RULE 1103. For Multiple Conformation or recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attached U.S.A. Inc. respectfully requests approval to retain the Temporarily Abasecondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# This Approval Of Abandonment Elements of the best of grade tank has been/will be constructed or closed according to NMOCD guidelines \(\D \), a get	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future expires expires my knowledge and belief. I further certify that any pit or below-
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# Abandonment E I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines \(\pri\), a get SIGNATURE Claude Bolling TITLE Regulation Title Regulation and the second of t	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future expires expires expires. Temporary expires e
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# This Approval Of Abandonment E	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future. Temporary Expires Temporary Telephone No. (432) 498-8662
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# This Approval Of Abandonment E	AER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future in future entered permit or an (attached) alternative OCD-approved plan entered permit or an (attached) alternative OCD-approved plan entered permit or an (attached) alternative OCD-approved plan entered permit or an entered
OTHER: Propose 13. Describe proposed or completed operations. (Clearly state all pertinof starting any proposed work). SEE RULE 1103. For Multiple Conor recompletion. This well was TA'd w/ CIBP set @ 5930'on 08/17/2000. Per the attache U.S.A. Inc. respectfully requests approval to retain the Temporarily Aba Secondary and CO2 Tertiary Recovery Operations. TD @ 8500' Perfs f/5982'-6026' 8-5/8" Csg @ 1500' 5-1/2" Csg. @ 8500' Initial Pressure: 540# 15 Min. Pressure: 540# 30 Min. Pressure: 540# This Approval Of Abandonment E	HER: Continue Temporary Abandon Status w/MIT Chart ent details, and give pertinent dates, including estimated date impletions: Attach wellbore diagram of proposed completion dintegrity test-chart performed on 11/11/2005, Chevron indoned Status of this wellbore for potential use in future in future expires where the proposed completion in the p



Churnon USA

Vaeu November II, 2005 Lehi

Surf = 0

Casing = 0

Key Energy

Steven Blowy