Submit 3 Copies To Appropriate District Office	State of New Mexico  y, Minerals and Natural Resources	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	y, winicials and water at Resources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL	CONSERVATION DIVISION	30-025-07171
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease  STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND I (DO NOT USE THIS FORM FOR PROPOSALS TO DRII DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)	LL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Oberholtzer
1. Type of Well: Oil Well Gas Well	Other	8. Well Number 1
2. Name of Operator	1,400	9. OGRID Number
Platinum Exploration, Inc.  3. Address of Operator		227103 10. Pool name or Wildcat
550 West Texas Avenue, Suite 500, Midland, 7	TX 79705	Gladiola (Devonian)
4. Well Location		
Unit Letter_ B:_660feet from the North line and 1980feet from the East_ line		
Section 8 Township 12S Range 38E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3862' KB		
Pit or Below-grade Tank Application or Closure	3	
Pit typeDepth to GroundwaterDi	istance from nearest fresh water well Dist	ance from nearest surface water
Pit Liner Thickness: mil Below-G	rade Tank: Volume bbls; Co	onstruction Material
12. Check Appropriat	e Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION PERFORM REMEDIAL WORK ☐ PLUG AN	N TO: SUB D ABANDON ☐ REMEDIAL WOR	SEQUENT REPORT OF:  K □ ALTERING CASING □
TEMPORARILY ABANDON  CHANGE		
PULL OR ALTER CASING MULTIPLI	<u> </u>	<del>_</del>
	Į.	
OTHER:	OTHER: Burn out	moraible numn
OTHER:  13. Describe proposed or completed operat	OTHER: Run sut	omersible pump  d give pertinent dates, including estimated date
13. Describe proposed or completed operation	ions. (Clearly state all pertinent details, and	omersible pump  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or completed operat of starting any proposed work). SEE R	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion // sub equipment. 230 jts 2 7/8 tbg set @
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion // sub equipment. 230 jts 2 7/8 tbg set @
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion // sub equipment. 230 jts 2 7/8 tbg set @
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion when subsequently subsequent
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion // sub equipment. 230 jts 2 7/8 tbg set @
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/tbg, SN & pkr. RIH w	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion when subsequently subsequent
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur 7974.6, btm pump set @ 8034.06. ND BOP RD</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/ tbg, SN & pkr. RIH wo PU.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion of sub equipment. 230 jts 2 7/8 tbg set @
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.</li> <li>11/11/05 – 11/14/05 MIRU PU, NU BOP &amp; ur</li> </ul>	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/ tbg, SN & pkr. RIH wo PU.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion of sub equipment. 230 jts 2 7/8 tbg set @
13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.  11/11/05 – 11/14/05 MIRU PU, NU BOP & ur 7974.6, btm pump set @ 8034.06. ND BOP RD  I hereby certify that the information above is true.	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At anset pkr. POOH w/ tbg, SN & pkr. RIH wo PU.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion of sub equipment. 230 jts 2 7/8 tbg set @
13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.  11/11/05 – 11/14/05 MIRU PU, NU BOP & un 7974.6, btm pump set @ 8034.06. ND BOP RD  I hereby certify that the information above is trugrade tank has been/will be constructed or closed accord.  SIGNATURE Slua Holcomb	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At moset pkr. POOH w/tbg, SN & pkr. RIH w PU.  e and complete to the best of my knowledging to NMOCD guidelines , a general permit   TITLE Agent  E-mail address: gholcomb@t3wirel	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE 11/29/05  ess.com Telephone No. 432-687-1664
13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.  11/11/05 – 11/14/05 MIRU PU, NU BOP & ur 7974.6, btm pump set @ 8034.06. ND BOP RD  I hereby certify that the information above is trugrade tank has been/will be constructed or closed accorded SIGNATURE  SIGNATURE  Type or print name  Gloria Holcomb  For State Use Only	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At moset pkr. POOH w/tbg, SN & pkr. RIH w PU.  e and complete to the best of my knowledging to NMOCD guidelines , a general permit   TITLE Agent  E-mail address: gholcomb@t3wirel	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE 11/29/05  ess.com Telephone No. 432-687-1664
13. Describe proposed or completed operation of starting any proposed work). SEE R or recompletion.  11/11/05 – 11/14/05 MIRU PU, NU BOP & un 7974.6, btm pump set @ 8034.06. ND BOP RD  I hereby certify that the information above is trugrade tank has been/will be constructed or closed accord.  SIGNATURE Slua Holcomb	ions. (Clearly state all pertinent details, and ULE 1103. For Multiple Completions: At user pkr. POOH w/tbg, SN & pkr. RIH w PU.	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan  DATE 11/29/05  ess.com Telephone No. 432-687-1664