•	New Mexico	OII Concernet		-	
Form 3160-5 August 1999) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS			971ve 8240	DD, District I FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000 5. Lease Serial No.	
Do not use this form for proposals to drill or to re-enter an				NM-18306	
abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE				6. If Indian, Allottee or Tribe Name	
				7. Unit or CA Agreement Name and No.	
1a. Type of Well 🗌 Oil Well 🗹 Gas Well 🔲 Other				8 Well Name and No.	
2. Name of Operator					Blanco 20 Federal 1
DEVON ENERGY PRODUCTION COMPANY, LP 3. Address and Telephone No.				API Well No.	0-025-37295
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198				10. Field and Pool, or Exploratory	
 Location of Well (Report location clearly and in accordance with Federal requirements)* 660 FSL 660 FWL 				Bell Lake; Atoka (Gas) 12. County or Parish 13. State	
				Lea	NM
CHEC	K APPROPRIATE BOX(s) TO IND		CE, REPORT, C	R OTHER DATA	
Notice of Intent	Acidize	Deepen		Start/Resume)	Water Shut-Off
Subsequent Report	Alter Casing	Fracture Treat New Construction	Reclamation		Well Integrity
Final Abandonment Notice	Change Plans	hange Plans 🛛 Plug and Abandon 🔲 Temp		Abandon	✓ Other <u>Drilling Operations</u>
13 Describe Proposed or Completed Operation deepen directionally or recomplete horizontally, giv	Convert to Injection S (Clearly state all pertinent details, and give pe	Plug Back	U Water Dispo	onosed work and appro-	ximate duration thereof. If the proposal
determined that the site is ready for final inspection 9/29/05 - 11/08/05 MIRU PU. RIH w/ bit and scra 13,460', 13530-13540'; 6 SPF. POOH w/ tbg, pkr, and guns. F RU and acidize w/ 3000 gals 7 13,487'. Acidize perfs 13,530- TOH w/ tubing and packer. RII perforated 13,226-13,236'; 30 F Acidize w/ 1500 gals 7.5% HCI Test plug to 1000 # - held good RIH w/ TCP assembly and set POOH w/ tbg, pkr, and guns. R 15% HCI and flushed w/ 49 bbl	per. POOH. TIH w/ TCP as Swab. Gas TSTM. RIH w/pkr and tbg. Set pkr @ 5% HCI w/ 20% Methanol ar 13,540' w/ 1500 gals 7.5% H H w/ CIBP and set @ 13,400 noles. POOH w/ guns. RIH w/ 20% Methanol. Swab we l. Dump bail 35' cement on pkr @ 12,479'. Perforate Ato IH w/ tbg and pkr and set @	 13,307'. Swab. 13,307'. Swab. 125,000 SCF N₂. S Cl and 71,668 SCF N '. Test plug and csg w/ tubing & pkr and s ell. Rel pkr and POO top of CIBP. bka 12,517-12,539 w/ 12,452'. Test csg to 	Swab well. 0 J ₂ Swab wel to 2700 psi - et @ 13,177 H w/ tbg and / 3 SPF. Swa 1000 # - hel	Gas TSTM. Re I. Gas TSTM. held good. RI . Test csg to 3 pkr. RIH w/ C ab. Slight gas d good. Acidiz	lease pkr and reset @ H w/ casing gun and 3000 # - held good. IBP to 13,190' and set. blow. Unset pkr and
14. Thereby certify that the foregoing is					DEC - 9 2005
	Name	Norvella Adam		G PETO	ARY GOURLEY
	Title	Sr. Staff Engineering Te		Date	12/1/2005
(This space for Federal or State Office	use)				
Approved by Conditions of approval, if any:	Title	TitleDate			
_		/		A PAN	
nue to 0.5.C. Secult foot, makes it a climetor an ts jurisdiction.	y person knowingly and willing to make any or	epariment of agency of the onneo	States any raise, non	ious or nauoulenr stater	nents or representations to any matter with
	*See In:	struction on Reverse Sid			