

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 05144 30-025-05144
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> X
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name T.D. POPE
8. Well Number 9
9. OGRID Number
10. Pool name or Wildcat Denton Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ Injection Well ☐

2. Name of Operator
STEPHENS & JOHNSON OPERATING COMPANY

3. Address of Operator
P.O. Box 2249, Wichita Falls, TX 76307-2249

4. Well Location

Unit Letter N : **660** feet from the **SOUTH** line and **1980** feet from the **West** line
Section **26** (SE SW) Township **14S** Range **37E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒ X
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 11-4-05 MIRU. Bleed off pressure.
11-5-05 Circ. well/w 10# MLF. Spot 75 sx. @7518'.
11-7-05 Tag plug @7242'. Spot 75 sx. @ 7242'.
11-8-05 Tag plug @ 6471'. Spot 75 sx. @4860'.
11-9-05 Tag plug @ 4450'. Found casing leak @ 441' - 378'. Spot 30 sx. @ 3150' - 3035'. Calc. T.O.C.
11-10-05 Spot 30 sx. @2200' - 2085'. Calc. T.O.C. Perf. 8 5/8" @517' as per OCD. Could not pump into perfs. RIH w/tbg. To 567'.
Spot 65 sx. @567'. Tag @305'.
11-11-05 Well had small amount of gassing. Called OCD, Billy Prichard. He authorized setting a CIBP. Set CIBP @ 250'. Spot 30
Sx. On top of CIBP 250' - 116'. Calc. T.O.C.
11-12-05 Well was dead. Spot 20 sx. @60' - surface.
RD MO.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE TITLE **AREA MANAGER** DATE: **12-01-05**

Type or print name **ROGER MASSEY** E-mail address: roger.massey@basicenergyservices.com Telephone No. **432-530-0907**

For State Use Only

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY: TITLE DATE **DEC 20 2005**

Conditions of Approval (if any):