## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		Revised 5-27-2004
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07481	
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreemen	nt Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) UNIT	
1. Type of Well: Oil Well X Gas Well Other			8. Well No. 131	
Name of Operator     Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, N 4. Well Location	NM 88240 505/397-82	200		
Unit Letter L : 2310	Feet From The SOUTH	Fee	et From The WEST	Line
Section 30	Township 18-S	Range 38-	E NMPM	LEA County
	11. Elevation (Show whether DF, RKB, 3656 GL	RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material  12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN		BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMENT		SATE OF WILLIAM
OTHER: CONVERT TO INJECTION		OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Pull production equipment.				$-\Delta$
2. Squeeze upper San Andres.			/ø'	20,
3. Acidize.			୍ /ର୍	DEC 1. File
<ul><li>4. Run injection equipment.</li><li>5. Notify NMOCD of packer test.</li></ul>			i line F.	Scalved B
6. Commence gas injection.			1 / 10	Hobbs (A)
Goodin's at a constant on the Con-	1 DVSV 007		* \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	OCD (A)
Gas injection granted under Admin Order PMX-237.				
				37326
I hereby certify that the information above is true				e constructed or
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	OCD-approved plan	1
SIGNATURE	7	TITLE Engineering Ad	visor DAT	E 12/14/05
TYPE OR PRINT NAME David Nelso	en E-mail address:		TELEPHONE NO.	505-397-8200
APPROVED BY  APPRO				
CONDITIONS OF APPROVAL IF ANY:				
Q . 144 C				
GWW				