Office Emonory Minard	f New Mexico s and Natural Reso	urcës			m C-103 ne 10, 2003	
1625 N. French Dr., Hobbs, NM 88240		13	WELL API NO.	30-025-2765		
	VATION DIVIS	~ ŭi	5. Indicate Type			
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505			STATE X FEE		
1220 S. St. Francis Dr., Santa Fe, NM	, , , , , , , , , , , , , , , , , , , 		-6. State OII & Ga B-2148	is Lease No.		
87505 SUNDRY NOTICES AND REPORTS O (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO	EPEN OR PLUG BACK	TO A	7. Lease Name of LEAMEX	r Unit Agreeme	nt Name	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other			8. Well Number	31	-	
2. Name of Operator ConocoPhillips Company			9. OGRID Numb	er 217817		
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762			10. Pool name or MALJAMAR GR		N ANDRES	
4. Well Location						
Unit Letter N : 660 feet from th	e SOUTH lin	ne and <u>l</u>	feet fro	om the WEST	line	
Section 24 Township 1			NMPM	County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4107' GL 4118' KB						
12. Check Appropriate Box to I NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK D PLUG AND ABANDO		SUB	SEQUENT REP ĸ□		ISING	
TEMPORARILY ABANDON 📙 CHANGE PLANS		ENCE DRI	LLING OPNS. 🗌	PLUG AND ABANDONME		
PULL OR ALTER CASING DULTIPLE COMPLETION		G TEST AN NT JOB	ID 🗌			
OTHER:		R: REPAIR	DOWN HOLE FA	ILURE	X	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 10/12/2005 12:00Unhang well, Rods stuck w/ heavy paraffin. MIRU hot wtr truck. Pump 35 bbls hot wtr down casing. 10/13/2005 07:00Found hole in body of third jt above the pump. RBIH w/ 148 jts, RU hot wtr truck to clean up tbg. Tbg plugged. POOH w/ 52 jts. found 12 jts plugged. 10/14/2005 07:00RU hot oil truck and pumped 40bbls hot wtr down tubing. POOH with 67 stands of tubing, Rigged up tubing testers to Psi test tubing BIH. Pick up 2 3/8" SN, 1 jt IPC (TK-99), 11 2 3/8" jts tubing, 4 1/2" TAC, and remainder of tubing, 138 jts. Found the 4th jt from bttm with a hole in tubing. Rigged down tbg testers, pick up work-floor, and removed BOP. Set TAC to 12 pts, flange well back on and got ready to run pump and rods. Close well. 10/17/2005 07:00Picked up pump with strainer nipple, 3 - 1.5" K-bars with centralizers between them and 2 - 3/4" KD guided rods pump action, pumping good,. Rig down 						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Day Thomas			s@conocophillips.c			
Type or print name Gay Thomas (This space for State use)	E-mail address:		E II/STAFF MANA	elephone No. (
APPPROVED BY Lary W. Wink Conditions of approval, if any:	OC FIELD REPRE			DATE	1 9 2005	