Submit 5 Copies to Appropriate District	Built of New Money		Form C-103 May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources NM 88240		WELL API NO.	7
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-29622 5. Indicate Type of Lease	10% 14
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE x FEE 6. State Oil & Gas Lease No.	_
1220 S. St. Francis Dr., Santa Fe, NM 87505	·		6. State Oil & Gas Lease No. 23000	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Eunice Monument South Unit	,
1. Type of Well: Oil Well Gas Well X Other Convert to Producer			8. Well Number 462	_
2. Name of Operator XTO ENERGY INC.			9. OGRID Number 5380	
3. Address of Operator 200 LORAINE STE 800 MIDLAND, TX 79701			10. Pool name or Wildcat Eunice Monument; Grayburg-San Andres	
4. Well Location	WIIDLAND, IA 19701		Lunice Monament, Grayout g Star 2 Marcs	\dashv
Unit Letter L: 259D feet from the S line and 50 feet from the w line				
Section 9	Township S21 Range		MPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
Pit or Below-grade Tank Application or Closure				
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water				
Pit Liner Thickness: mil	Below-Grade Tank: Volume		onstruction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WOF	RILLING OPNS. P AND A	ם
OTHER: X CONVERT TO P	PODUOTA	OTHER:	· · · · · · · · · · · · · · · · · · ·	T
13. Describe proposed or completed operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date				
or recompletion. PROCEDURE TO CONVERT TO PRODUCER MIRU, NDWH, NUBOP, RIH W/CSG SCRPR RIH, SET CIBP @4275', DUMP 35' ON TOP, TST CSG TO 500 PSI PERF UPPER SAN ANDRES 4118-40, 4160-70, 4186-94 ACD W/4.5 BBLS ACD ACROSS PERFS, ACD W/3000 GALS 15% NEFE HCL 30 BALLS/EVERY 10 BBLS SWB RIH W/PROD EQPT. SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PK'R AND RBP				
SUPPLEMENTAL PROCEDURE FOR RUNNING LINER POOH W/PKR AND RBP RIH TO CIBP W/5 ½" FLOAT SHOE, 1 JT 5 ½" CSG, LND COLLAR 1000' 5 ½" CSG AND LNR, CMT LNR, POH, WOC D/O CMT TOP OF LNR, TST LNR TOP TO 500 PSL, POH C/O LNR, TST TO 500 PSL, POH PERF/ACD AS ABOVE				
	TE/PSI, POH W/PKR AND RBP LEAK, CIRC THRU CICR, SQZ LEAK ND CMT TO 4240', TST SQZ TO 500 PSI, I	РОН		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.				
SIGNATURE DATE 11/18/2005				
Type or print name M. LYN M For State Use Only	, ,		DEC 0	
APPROVED BY: Hour Conditions of Approval (if any)	Winks OC FIELD	REPRESENTATIV	TE II/STAFF MANAGER DEC 2	— T (003