Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-025-25925	· · · · · · · · · · · · · · · · · · ·
1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		<ol> <li>Indicate Type of Lease STATE</li></ol>	e FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	7505	6. State Oil & Gas Lease L 6379	e No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit	Agreement Name
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other		Horseback 8. Well Number	6	
2. Name of Operator			9. OGRID Number <b>25078</b>	
Whiting Oil & Gas Corporation  3. Address of Operator			10. Pool name or Wildo	at
400 W. Illinois, Suite 1300, Midland, TX 79701			Comanche Statelin	
4. Well Location  Unit Letter A: 990 feet from the North line and 990 feet from the East line				
Section 33		ange <b>36-E</b>	NMPM Lea	County
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)		4
Pit or Below-grade Tank Application	2,899' G or Closure ⊠	L		
Pit type_STEEL_Depth to Groundwat		ater well> 1 mile_	Distance from nearest surf	ace water_> 1 mile
Pit Liner Thickness: STEEL	mil Below-Grade Tank: Volume	180 bbls; Co	onstruction Material S	TEÉP
12. Check Appropriate Box to Indicate Nature of Notice, Report of Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
TEMPORARILY ABANDON		1 44 24	D'A ⊠	
PULL OR ALTER CASING  OTHER:	MULTIPLE COMPL	CASING/CEMENT OTHER:	ر I JOB /رئا⊓	
	pleted operations. (Clearly state all p		I give pertinent dates, incl	uding estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
12/13/05 thru 12/15/05				
Notified NMOCD, Sylvia Dickey. MIRU Triple N rig #25 and plugging equipment, set steel working pit. Set CIBP @ 3,036'. Circulated hole w/ mud and pumped 25 sx C cmt on CIBP 3,036 – 2,795'. Pumped 25 sx C cmt 2,125 – 1,884'. Cut casing @ 1,448', not free, unable to pump thru cut at 1,500 psi. Pumped 25 sx C cmt @ 1,487'. WOC & tagged cmt @ 1,112'. Cut & pulled 5½'casing FROM 856'. RIH w/ tbg and pumped 35 sx C cmt w/ 2% CaCl <sub>2</sub> @ 896'. WOC and tagged cmt @ 730'. Circulated 55 sx C cmt 216' to surface. POOH w/ tbg, ND BOP. RDMO.				
Cut off wellhead, installed dry hole marker, cut off anchors.				
		Liabi	roved as to plugging of lity under bond is retain use restoration is compl	ned until
		5	or restoration is compr	cucu.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.				
À a	44			
SIGNATURE	TITLE _	Petroleum Eng	gineerDAT	E <u>12/21/05</u>
Type or print nameJames F. Newman, P.EE-mail address:jim@triplenservices.com Telephone No432-687-1994 For State Use Only				
A I I I I I				
Conditions of Approval (if any).  APPROVED BY:  JAN 0 4 2006				