`1Submit 3 Copies To Appropriate District Office	State of New Mex	xico		Form C-103
District I	Energy, Minerals and Natur	ral Resources	WELL ADINO	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-37569	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Type	of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE [
District IV	Santa Fe, NM 87	505	6. State Oil & Ga	is Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Anger State		
PROPOSALS.)	,		8. Well Number	
1. Type of Well: Oil Well ⊠ Gas Well □ (Ithar		#1	
<u> </u>	Julei		0 OCRID Numb	
2. Name of Operator Nadel and Gussman Permian, LLC			9. OGRID Numb 155615	Wildcat West
3. Address of Operator			10. Pool name or	Wildcat
601 N. Marienfeld Suite 508 Midland	l, Texas 79701		Hume Grayburg	West 'S
4. Well Location				50 06.
Unit Letter H · 16	; O'feet from theNorth li	ine and 330'	feet from the	a line
Oint Letter11,0_	icet from theivorth if			A STATE OF
	nship 16-S Range 33-E	NMPM	County	102 4 14
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	7,67	
Pit or Below-grade Tank Application (For p		C-144 must be attached		
Pit Location: UL _H_ Sec _15_Twp _16-S_R	<u> </u>			Fresh water well 1,000'+
Distance from nearest surface water 1000'+				
			r	_'
feet from the line and	feet from the line			
feet from theline and	feet from theline			
		(2) / F	0.1	
12. Check Ap	opropriate Box to Indicate Na		-	
12. Check Ap	opropriate Box to Indicate Na ENTION TO:	SUBS	EQUENT RE	PORT OF:
12. Check Ap	opropriate Box to Indicate Na ENTION TO:		EQUENT RE	
12. Check Approved NOTICE OF INT	opropriate Box to Indicate Na ENTION TO:	SUBS	EQUENT RE	PORT OF: ALTERING CASING PLUG AND
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK	opropriate Box to Indicate Na ENTION TO: PLUG AND ABANDON □ CHANGE PLANS ☑	SUBS REMEDIAL WORK COMMENCE DRIL	EQUENT RE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK	ppropriate Box to Indicate Na ENTION TO: PLUG AND ABANDON	SUBS REMEDIAL WORK	EQUENT RE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ITEMPORARILY ABANDON PULL OR ALTER CASING	ppropriate Box to Indicate National TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design	propriate Box to Indicate Na ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work	ppropriate Box to Indicate National TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended pertinent details, and	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro	ppropriate Box to Indicate National TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple popose to change the casing string of the complete of the casing string of the	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended Description details, and the Completions: Attach	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr 1. NGP is proposi	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion and to drill a 12 ¼" hole to
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8° casing and cemerate.	ppropriate Box to Indicate National TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple popose to change the casing string of the complete of the casing string of the	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended Description details, and the Completions: Attach	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr 1. NGP is proposi	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion and to drill a 12 ¼" hole to
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro	ppropriate Box to Indicate National TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple popose to change the casing string of the complete of the casing string of the	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended Description details, and the Completions: Attach	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr 1. NGP is proposi	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion and to drill a 12 ¼" hole to
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ITEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500' and run 8 5/8" casing and cemes surface.	propriate Box to Indicate Natice Partion To: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple phose to change the casing string cent to surface. Then continue with	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended Description the details, and the Completions: Attached the Anger State # the 7 7/8" hole to 4	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr NGP is proposis 800' and run 5 ½'	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion ing to drill a 12 ¼" hole to 'casing and cement to
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8° casing and cemerate.	propriate Box to Indicate Natice Particle To: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple phose to change the casing string cent to surface. Then continue with	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Description that details, and the Completions: Attached the Anger State #	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr NGP is proposi 800' and run 5 ½' and belief. I furth	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion ing to drill a 12 ¼" hole to casing and cement to
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8" casing and cemes surface. I hereby certify that the information al grade tank has been/will be constructed or classification.	propriate Box to Indicate Natice Particle To: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all parts). SEE RULE 1103. For Multiple phose to change the casing string control to surface. Then continue with cover is true and complete to the become according to NMOCD guidelines property of the pr	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Descriment details, and the Completions: Attach on the Anger State # the 7 7/8" hole to 4. Test of my knowledge S, a general permit 0	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr 1. NGP is proposi 800' and run 5 ½' and belief. I furth or an (attached) altern	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion ing to drill a 12 ¼" hole to 'casing and cement to er certify that any pit or belownstive OCD-approved plan
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC proposed and run 8 5/8" casing and cemes surface.	propriate Box to Indicate Natice Particle To: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple phose to change the casing string cent to surface. Then continue with	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Descriment details, and the Completions: Attach on the Anger State # the 7 7/8" hole to 4. Test of my knowledge S, a general permit 0	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagr 1. NGP is proposi 800' and run 5 ½' and belief. I furth or an (attached) altern	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion ing to drill a 12 ¼" hole to 'casing and cement to er certify that any pit or belownstive OCD-approved plan
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8" casing and cemes surface. I hereby certify that the information al grade tank has been/will be constructed or classification.	propriate Box to Indicate Nate of ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all plants) for Multiple opose to change the casing string of the to surface. Then continue with cove is true and complete to the besord according to NMOCD guidelines.	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Descriment details, and the Completions: Attach on the Anger State # the 7 7/8" hole to 4. Test of my knowledge S, a general permit 0	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagnosis 800° and run 5 ½° and belief. I further an (attached) altern DATE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion ing to drill a 12 ¼" hole to casing and cement to er certify that any pit or belownative OCD-approved plan 12/29/05
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ITEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8" casing and cemes surface. I hereby certify that the information all grade tank has been/will be constructed or classification. Type or print name Josh Fernau	propriate Box to Indicate Nate of ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all plants) for Multiple opose to change the casing string of the to surface. Then continue with cove is true and complete to the besord according to NMOCD guidelines.	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Description details, and the Completions: Attached the Anger State # The 17/8" hole to 4. Test of my knowledge and the Anger State # Test of my knowledge and the Staff Engineer	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagnosis 800° and run 5 ½° and belief. I further an (attached) altern DATE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion ing to drill a 12 ¼" hole to casing and cement to er certify that any pit or belownative OCD-approved plan 12/29/05
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8" casing and cemes surface. I hereby certify that the information algrade tank has been/will be constructed or cleaning the cleaning the cleaning the constructed or cleaning the cleanin	propriate Box to Indicate Nate of ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all plants) for Multiple opose to change the casing string of the to surface. Then continue with cove is true and complete to the besord according to NMOCD guidelines.	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Description details, and the Completions: Attached the Anger State # The 17/8" hole to 4. Test of my knowledge and the Anger State # Test of my knowledge and the Staff Engineer	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagnosis 800° and run 5 ½° and belief. I further an (attached) altern DATE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion ing to drill a 12 ¼" hole to casing and cement to er certify that any pit or belownative OCD-approved plan 12/29/05
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ITEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500° and run 8 5/8" casing and cemes surface. I hereby certify that the information all grade tank has been/will be constructed or classification. Type or print name Josh Fernau	propriate Box to Indicate Nate of ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all plants) for Multiple opose to change the casing string of the to surface. Then continue with cove is true and complete to the besord according to NMOCD guidelines.	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Description details, and the Completions: Attached the Anger State # The 17/8" hole to 4. Test of my knowledge and the Anger State # Test of my knowledge and the Staff Engineer	LING OPNS. LING OPNS. D I Report give pertinent dat ach wellbore diagnosis 800° and run 5 ½° and belief. I further an (attached) altern DATE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion ing to drill a 12 ¼" hole to casing and cement to er certify that any pit or belownative OCD-approved plan 12/29/05
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ITEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Change Casing Design 13. Describe proposed or comple of starting any proposed work or recompletion. Nadel and Gussman Permian, LLC pro 1,500' and run 8 5/8" casing and cemes surface. I hereby certify that the information all grade tank has been/will be constructed or clean surface. Type or print name Josh Fernau Josh Fernau Type or print name Josh Fernau Josh Fernau This space for State use)	propriate Box to Indicate Nate of ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly state all pk). SEE RULE 1103. For Multiple opose to change the casing string cent to surface. Then continue with cove is true and complete to the become decording to NMOCD guidelines TITLE E-mail address: jo	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AND CEMENT JOB OTHER: Amended Description details, and the Completions: Attached the Anger State # The 17/8" hole to 4. Test of my knowledge and the Anger State # Test of my knowledge and the Staff Engineer	LING OPNS. LING OPNS. D I Report give pertinent date and wellbore diagnorm. NGP is proposis 800° and run 5 ½² and belief. I further an (attached) alternan (attached) alternan (attached) alternan (attached).	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date am of proposed completion ing to drill a 12 ¼" hole to casing and cement to er certify that any pit or belownative OCD-approved plan 12/29/05 2-682-4429