Submit 3 Copies To Appropriate District Office	State of N				Form C-10 Revised March 25, 199	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals a	ina Natu	ral Resources	WELL API NO	Kevised March 25, 199	
District II	OIL CONSERV	ATION	DIVISION	30 025 04381		
811 South First, Artesia, NM 88210 District III	2040 Soi			5. Indicate Type	of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe			STATE	FEE	
District IV 2040 South Pacheco, Santa Fe, NM 87505	Sunta 1 C	, 1111 07	505	6. State Oil & 0	Gas Lease No.	
SUNDRY NOTIO	CES AND REPORTS ON	WELLS			or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC.				STATE E-33	C	
PROPOSALS.)	TION FOR FERMIT (FORM	4 C- 101) FC	N SOCH			
1. Type of Well:						
Oil Well Gas Well 2. Name of Operator	Other			8. Well No.	3	
FINLEY RESOURCES, I	NC.			o. wenno)	
3. Address of Operator				9. Pool name or		
1308 LAKE ST. SUITE 200, F	ORT WORTH, TEXAS	76102		EUMONT YATE	ES SEVEN RIVERS	
4. Well Location			1980			
Unit Letter F1650_	feet from theNORTH	liı	ne and 2340	feet from the	WESTline	
Section 33	Township 20 10. Elevation (Show w		Range 36E		LEA County	
	•	07' RKB	ς, <u>ΜΩ</u> , <u>Μ</u> , <u>Μ</u> , <u>Μ</u> , εις	·· /		
	ppropriate Box to Ind	licate Na	ature of Notice, I	Report or Other	Data	
NOTICE OF IN		_		SEQUENT <u>R</u> E		
	PLUG AND ABANDON		REMEDIAL WORI	к 🗆	ALTERING CASING	
	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB			
OTHER:			OTHER: Temp	porary Abandonme	nt l	
 Describe proposed or complete of starting any proposed work). or recompilation. 						
or recompnation.						
Casing leak from 768-1352'. Set CI Displace 2 bbls. Tag cmt @ 798'. S	BP @ 3793' (77' above p	perfs) & terms 00° WO	ested to 1000#. Spot	t 95 sx Cl.C +2% C Pressure test csg 5	NOT 3 SHOW NOW	
Test witnessed by J. Robinson of N	MOCD. Request approva	l of TA st	atus.			
_				15 1		
This Approval o	f Temporary 12	link	0	(40 (40	Ning 8	
Abandonment E	xpires	19/10	2	40		
		7	-	(e)	& HOND VY	

100 I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE James	1. Hanne		T MANAGER DATE 1/3/06
Type or print name	JAMES L. NANCE	Telephone No.	(817) 231-8727
(This space for State use) APPPROVED BY Conditions of approval, if any	yw. Wink	UC FIELD REPRESENTATIVE	IVSTAFF MANAGER

Ø.C

Q20



H r { 6 %	ley sources Inc. Operations Report	Geology	Doug Harringtor	214 763-6092
1 71/64	STATE "E' 33 #3	Operations	Jim Nance	817 832-363
	LEA COUNTY, NEW MEXICO	Site Supv		915 466 1737
		Rig		PHONE #
DATE	ACTIVITY	Foreman	DAILY COST	CUM COST
	MIT			
11/01/05	MIRU 3 D Well Service. (Jose Castro-Operator) POH LD PR 1-1/4 'x16', PRL 1-1/2"x 8', 3/4" subs, 2,6, 52-3/4" rods, 99-5/8" rods, 2"x14' pump. RDMO.	JGW	\$2,000	\$2,000
12/01/05	MIRU 3 D Well Service. (Jose Castro-Operator) NDWH. NUBOP. POH LD 127 jts 2 3/8" tbg, SN, PS, MJ w/ notch collar. SDFN.	JGW	\$2,000	\$4,000
12/02/05	CTL. RIH w/ 4 3/4" bit, csg scrapper (Hudson), PU 116 jts 2 3/8" WS off trailer to 3570'. POH w/ tbg, scrapper & bit. Wind blowing. SDFD	JGW	\$7,300	\$11,300
12/03/05	CTL. RIH w/ 5 1/2" RBP & pkr. Set RBP @ 3505' & Pate pump trk test to 1000#-OK. Circ csg in Serria vac trk. (Called John Roberson w/ OCD on 12/2/05 Fri-told him we were going to test csg (MIT) on 12/2/05 Sat. He said go ahead every one was off except for emergencies). Test csg to 500#-Bled off 250# in 3 min. No circ to surface. NOTE: MIT test failed. Isolate csg leaks 768' to 1352' (584'). POH w/ pkr & SDFN.		\$8,200	\$19,500
12/04/05	SDFWE			
12/05/05	CTL. POH w/ tbg & pkr. NDBOP. Dig out well head. ND tbg head. 5 1/2" csg welded to 8 5/8" surface csg head. Called Doug Howell about csg. Will not be able to free point 5 1/2" csg without cutting wellhead off. Talked w/ Doug Howell, Jim Nance & Chris Williams (NMOCD District Superintendent) about procedure to TA well. Ring gasket needed replacing but unable to find new one. Teflon tape old ring gasket & NUWH. NUBOP. Prep to RIH & retrieve RBP. SDFN.	JGW	\$4,900	\$24,400
12/06/05	CTL. RIH w/ retrieving head to 3505', latch on RBP & POH. RIH w/ 4 3/4" bit, 5 1/2" csg scrapper on 2 3/8" WS to 3871', tag, set 3000# on bit. POH w/ tbg scrapper & bit. W.O.O. Talk w/ Bill Shockley & permission given to go in hole w/ CIBP. RIH w/ 5 1/2" CIBP (Hudson-Weatherford) on WS to 3823'-unable to set CIBP. Pull to 3793' & set CIBP (77' above top perf @ 3870'). POH w/ tbg & setting tool. Prep to RIH w/ pkr, test CIBP & circ pkr fluid. SDFN.	JGW	\$6,300	\$30,700
12/07/05	CTL. Air lines froze on pulling, thaw out. RIH w/ pkr on WS to 3760'. Majority pump truck PSI RBP 1000#-OK. Circ csg w/ packer fluid (Unichem/BJ Hughes Techni-Hib 370, mix 1% in fresh water). POH w/ tbg & pkr. (Temp stay below freezing all day). SDFN		\$7,100	\$37,800
12/08/05	CTL. W.O.O. SDFN	JGW	\$4,000	\$41,800
12/09/05	CTL. RIH w/ 119 jts WS to 3657'. NDBOP, NUWH. (Move to ST. "E" 33 #2)RDMO. MIRU, (Move back from ST. "E" 33 #2) NDWH, NUBOP. SDFN.		\$2,000	\$43,800
12/10/05 -	SDFWE		\$0	
12/11/05	SDFWE		\$0	
12/12/05	CTL. (Move to Federal "D" #3 due to cmt job cancel) RDMO	JGW	\$3,500	\$3,500
	TA Well		\$0	
12/15/05	MIRU. 3 D Well Service (Jose Castro-Operator) POH LD 80 jts WS. Left 46 jts 2-3/8" tbg in hole w/ btm @ 1415'. Prep to pump cmt in a.m. Called Buddy Hill w/ NMOCD to alert him of cmt job & MIT test to TA well. SDFN.	JGW	\$3,800	\$3,800
12/16/05	CTL. RU BCM & Assoc., Majority transport w/ fresh water & vac trk. Spot 95 sxs Cl. "C" w/ 2 cacl2 from 1415' to 500' (915'). POH LD 30 jts 2 3/8" WS. Rev circ from 493'. Pump 2 bbls displacement @ 100#-SI WOC. 4 hr SI-cmt still green. SDFN	JGW	\$9,900	\$13,700
12/17/05	CTL. RIH w/ 2 3/8" WS & tag cmt @ 798' (148' to low). BCM spot 30 sxs Cl "C" neat cmt from 798' to 509' (289'). POH w/ tbg. Took 1 bbl to load csg. Prep to tag cmt & test csg to 500#, SDFN.	JGW	\$5,900	\$19,600
12/18/05	SDFWE		\$0	
12/19/05	CTL. RIH w/ tbg. Tag cmt @ 500'. POH LD tbg. NDBOP & NUWH. Call Johnny Robinson w/ NMOCD about MIT to TA well. Psi to 640#. Went to 615# in 55 min. (Lost 25#) Johnny showed to witness test & said up to 10% loss OK. He signed chart. NOTE: Passed MIT for TA. Change status of well to TA. RDMO.	JGW	\$4,500	\$24,100

