Form 3160-5 (JUNE 1990)

UNITED STATES OCD-HOBBS

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** FORM APPROVED

Budget Bureau No. 1004-0135 Expires: March 31, 1993

5.	Lease	Designation	and	Serial	No.

•				
	NIN	۸.	77058	

SUNDRY NOTICES	S AND REPORTS ON WELLS	NM-77058		
Do not use this form for proposals to o	6. If Indian, Allottee or Tribe Name			
	I FOR PERMIT-" for such proposals			
1. Type of Well	7. If Unit or CA, Agreement Designation			
Oil Gas				
X Well Well Other		8. Well Name and No.		
2. Name of Operator STRATA PF	Cercion Federal #5 9. API Well No.			
3. Address and Telephone No. P. O. Box 1	30-025-31849			
Roswell, Ne	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Sur	rvey Description)	Livingston Ridge Delaware East		
330' FNL &		11. County or Parish, State		
Section 21-2	2S-32E	Lea County, New Mexico		
12. CHECK APPROPRIATE BO	X(s) TO INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	X Abandonment	Change of Plans		
	Recompletion	New Construction		
X Subsequent Report	Plugging Back	Non-Routine Fracturing		
	Casing Repair	Water Shut-Off		
Final Abandonment Notice	Altering Casing	Conversion to Injection		
	OTHER	(Note: Report results of multiple completion on Well		
01/05/06: POOH w/315 ro 01/06/06: POOH w/tbg, 24 to 6900'. Circ 1 5820' - 5630'. F 01/09/06: POOH w/remair SD due to high 01/10/06: POOH w/98 jnts Will tag. 01/11/06: RIH and tag at 4 at 930'. POOH at 550'. POOH	ified BLM. MI steel pit. POOH w/107 rods ods. NUBOP. Unset TAC. POOH w/tbg, 49 jnts. RIH & set CIBP @ 7100'. Dump 30# mud. Close BOP. Test csg to 1000#. POOH. SI. ning tbg. NDWH. Weld on pull nipple. Cowinds to protect threads. 5 5 1/2" csg. NUBOP. RIH and spot 60 sx 4043'. POOH and spot 25 sxs 2600' - 250 WOC. Tag at 815'. POOH and spot 35 and spot 20 sxs at 60' to surface. SD. stall dry hole marker. Level. Move out.	109 stnds. LD 15 jnts. SI. 35' cmt on top. RIH w/tbg POOH & spot 25 sxs at ut csg at 4185'. LD 8' jnts. cs at 4515'. POOH. SI. \$\frac{000}{500} \text{ sq00H} \text{ DOM: POOH and spot 35 sxs}		
	·			
14. Thereby certify that the foregoing is true a	and correct			
Signed Lum Month	Title Production Records	Date 01/13/06		
(This space for Federal or State office use) Approved by CD DAVID & CL Conditions of approval, if any:	Title FETROLEL 241 ENGINEE	Date JAN 18 2006		
Conditions of approval, if any:	erson knowingly and willfully to make to any department or agency of the U			