Office	State of New Me	exico	Form C-103
District I	Energy, Minerals and Natu	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-34915
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION F	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE STATE
District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTIC	CES AND REPORTS ON WELLS	!	VA-1351-1  7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLU	UG BACK TO A	7. Lease Name of Onit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FO	DR SUCH	Angel State 13 Com
· · · · · · · · · · · · · · · · · · ·	Gas Well 🔲 Other		8. Well Number
2. Name of Operator	V-11-2		9. OGRID Number
Ameristate Exploration LLC			9. OGRID Number 158898
3. Address of Operator			10. Pool name or Wildcat
111 Congress Ave., Suite 2700, Austin, TX 78701			Lovington, Upper San Andres, West
4. Well Location			
Unit Letter A:_660 feet fro	m the north line and 660 feet from	m the East line	
Section 13 Township		PM Lea County	
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or	3,909' GL		
	terDistance from nearest fresh w	oter well Distor	no from pagrant surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume		struction Material
12. Check A	ppropriate Box to Indicate N	ature of Notice, R	eport or Other Data
NOTICE OF INT	· - · · - · - ·	SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK	☐ ALTERING CASING ☐
		i .	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	LING OPNS. P AND A
TEMPORARILY ABANDON		COMMENCE DRILE CASING/CEMENT	LING OPNS. P AND A
TEMPORARILY ABANDON DULL OR ALTER CASING DUTHER:	CHANGE PLANS	CASING/CEMENT OTHER:	LING OPNS. P AND A D
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete	CHANGE PLANS  MULTIPLE COMPL  Detected operations. (Clearly state all parts)	CASING/CEMENT OTHER: Description of the control of	JOB D
TEMPORARILY ABANDON PULL OR ALTER CASING DOTHER:  13. Describe proposed or complet of starting any proposed work.	CHANGE PLANS  MULTIPLE COMPL  Detected operations. (Clearly state all particle). SEE RULE 1103. For Multiple	OTHER: Dertinent details, and le Completions: Atta	JOB Date of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete	CHANGE PLANS  MULTIPLE COMPL  Detected operations. (Clearly state all particle). SEE RULE 1103. For Multiple	OTHER: Dertinent details, and le Completions: Atta	JOB Date of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all post)  k). SEE RULE 1103. For Multip	OTHER: Dertinent details, and le Completions: Atta	JOB D  give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well per starting and proposed work or recompletion.	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all post)  k). SEE RULE 1103. For Multip	OTHER: Dertinent details, and le Completions: Atta	JOB Date of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or complet of starting any proposed wor or recompletion.  Temporarily abandon well put of MIRU W/O rig.	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all post)  k). SEE RULE 1103. For Multip	OTHER: Dertinent details, and le Completions: Atta	JOB D  give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well put of the pull of	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all pk). SEE RULE 1103. For Multiple cter procedure below:	CASING/CEMENT OTHER: pertinent details, and le Completions: Atta	JOB D  give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well put of the pull of	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all post)  k). SEE RULE 1103. For Multip	OTHER: Dertinent details, and le Completions: Atta	JOB D  give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Temporarily abandon well pull MIRU W/O rig.  2) Pull rods and tubing.  3) Set CIBP at approximate	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all pk). SEE RULE 1103. For Multiple cter procedure below:	OTHER: Dertinent details, and le Completions: Atta	JOB D  give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well put of the pull of	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all pk). SEE RULE 1103. For Multiple cter procedure below:	OTHER: Dertinent details, and le Completions: Atta	JOB Date of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well put of the public of the public of starting and the public of starting and the public of starting and the public of the public	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all percent)  cted operations. For Multiple of the procedure below:  cted operations (Clearly state all percent)  cted operations (Clearly	OTHER: Description details, and le Completions: Atta	ING OPNS. PAND A DOB
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well pull pull pull pode and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all petch.) SEE RULE 1103. For Multiple cter procedure below:  ctely 4750' and dump 35' cement	OTHER: Description to details, and le Completions: Atta	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well pull pull pull pode and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all petch.) SEE RULE 1103. For Multiple cter procedure below:  ctely 4750' and dump 35' cement	OTHER: Description to details, and le Completions: Atta	ING OPNS. PAND A DOB
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complet of starting any proposed work or recompletion.  Temporarily abandon well pull pull pull pode and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all plants). SEE RULE 1103. For Multiple er procedure below:  clearly 4750' and dump 35' cement  bove is true and complete to the belowed according to NMOCD guidelines	OTHER: Description to details, and le Completions: Atta	And belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Temporarily abandon well put of the pull rods and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a grade tank has been/will be constructed or a signal rods.	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all per procedure below:  ctely 4750' and dump 35' cement  bove is true and complete to the belosed according to NMOCD guidelines [TITLE V	CASING/CEMENT OTHER: pertinent details, and le Completions: Atta	and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan  DATE 31 January 2006
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Temporarily abandon well pull pull pull pull pull pull pull p	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all per procedure below:  ctely 4750' and dump 35' cement  bove is true and complete to the belosed according to NMOCD guidelines [TITLE V	CASING/CEMENT OTHER: pertinent details, and le Completions: Atta	and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan  DATE 31 January 2006
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Temporarily abandon well put of the pull rods and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a grade tank has been/will be constructed or a signal rods.	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all per procedure below:  ctely 4750' and dump 35' cement  bove is true and complete to the belosed according to NMOCD guidelines [TITLE V	CASING/CEMENT OTHER: pertinent details, and le Completions: Atta	and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan  DATE 31 January 2006
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Temporarily abandon well put of the pull rods and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a grade tank has been/will be constructed or a signal rods.	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all per procedure below:  ctely 4750' and dump 35' cement  bove is true and complete to the belosed according to NMOCD guidelines [TITLE V	CASING/CEMENT OTHER: pertinent details, and le Completions: Atta	and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan  DATE 31 January 2006
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR AL	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all plants). SEE RULE 1103. For Multiple er procedure below:  cely 4750' and dump 35' cement  bove is true and complete to the belowed according to NMOCD guidelines.  TITLE Y  E-mail address	CASING/CEMENT OTHER: Destrinent details, and le Completions: Atta	and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan  DATE 31 January 2006  Telephone No.: 512.391.0300
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion.  Temporarily abandon well putter of the pull rods and tubing. 2) Pull rods and tubing. 3) Set CIBP at approximate 4) Load and test casing.  I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE  Type or print name: Michael Arguijo	CHANGE PLANS  MULTIPLE COMPL  cted operations. (Clearly state all plants). SEE RULE 1103. For Multiple er procedure below:  cely 4750' and dump 35' cement  bove is true and complete to the belowed according to NMOCD guidelines.  TITLE Y  E-mail address	CASING/CEMENT OTHER: pertinent details, and le Completions: Atta	and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan  DATE 31 January 2006  Telephone No.: 512.391.0300