

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-35175
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. VA-1351-1
7. Lease Name or Unit Agreement Name Angel State 13
8. Well Number 2
9. OGRID Number 158898
10. Pool name or Wildcat Vacuum; Blinebry, Northeast

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Ameristate Exploration LLC

3. Address of Operator
111 Congress Ave., Suite 2700, Austin, TX 78701

4. Well Location
Unit Letter A: 2310 N 230 E
660 feet from the north line and 660 feet from the East line
Section 13 Township 17-S Range 35-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,918' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: Perform bradenhead squeeze prior to T & A ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Repair and T&A well per following procedure:

- 1) MIRU W/O rig.
- 2) POOH with rods and tubing.
- 3) RIH and set RBP. POOH. RBIH w/packer testing tubing and backside to locate holes in production casing.
- 4) Rig up cementers and pump bradenhead squeeze.
- 5) Drill out cement and test casing.
- 6) Wait on orders and permits to recomplete and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Michael Arguijo TITLE Vice President -Operations DATE 31 January 2006

Type or print name: Michael Arguijo E-mail address: m.arguijo@mdtrn.com Telephone No.: 512.391.0300

For State Use Only

APPROVED BY: Ray W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____

Conditions of Approval (if any):

FEB 07 2006