## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION		
DISTRICT I	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO.	
1625 N. French Dr. , Hobbs, NM 88240			30-025-07490  5. Indicate Type of Lease	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			8. Well No. 411	
Type of Well:     Oil Well     X	Gas Well Other		6. WEILING. 411	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.			10. Pool name or Wildcat	HOBBS (G/SA)
Address of Operator     1017 W. Stanolind Rd., HOBBS, NM 88	8240 505/397-820	0	10. 1 col hanz of wheeat	HODDS (G/SA)
4. Well Location				
Unit Letter A : 330	Feet From The NORTH	Feet	From The EAST	Line -
Section 31	Township 18-S	Range 38-E	NMPM	LEA County
<i><b>XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</b></i>	11. Elevation (Show whether DF, RKB, RS 3645 GL	GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PI	LUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON CI	HANGE PLANS	COMMENCE DRILLING OPNS	. PLUG & AE	SANDONMENT
	ultiple Completion	CASING TEST AND CEMENT	JOB 🗍	
OTHER: Add perforations and AT	$\overline{\mathbf{x}}$	OTHER:	<b>L</b>	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Pull production equipment.			04.25.2	
<ul><li>2. Perforate 4150-55 and Acid stimulate.</li><li>4. Run production equipment.</li></ul>		60	232425262	76
With production 14-phila		John State	4	) <b>U</b>
		*	0000 /	
			20,0	
		. 14 1500 1000	he	
		3,	\$ A.7	
		₹0	r. 9/	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit of below: grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan				
closed according to NMOCD guidelines	, a general permit	•		1 1 1
SIGNATURE		TITLE Engineering Adv	isor DATE	1/3//04
TYPE OR PRINT NAME David Nelson	E-mail address:		TELEPHONE NO.	505-397-8200
For State Use Only				
APPROVED BY	ump of	REPRESENTATIVE	IL/STAFF MANAGEDAT	E
CONDITIONS OF APPROVAL IF ANY:				