State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV.	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-02	5-29276
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE Lee V	
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 28	
1. Type of Well: Oil Well Gas Well Other Injector			8. Well No. 242	
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NA	A 88240 505/3	97-8200		MODDS (G/S/1)
4. Well Location			2324 25 200	
Unit Letter N : 1166	Feet From The SOUTH	Fee	et From The WEST	Line
Section 28	Township 18-S	Range 38-		LEA County
	11. Elevation (Show whether DF, Ri 3644' GR	KB, RI GR, etc.)	Sciller	
Pit or Below-grade Tank Application	or Closure	1.5	Carlotte Carlotte	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
1	Below-Grade Tank: Volume	1	,	
12. Check A	nnronriata Roy to Indicate No	ture of Notice Penart or	Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK F	PLUG AND ABANDON	REMEDIAL WORK	X ALTERIN	G CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	NS. PLUG &	ABANDONMENT
PULL OR ALTER CASING N	Multiple Completion	CASING TEST AND CEME	=	
	vidiliple Completion		11 308	
OTHER:		OTHER:		
13. Describe Proposed or Completed Opera proposed work) SEE RULE 1103. For				starting any
1. RUPU. Pull Injection equipment.				
2. Clean out to PBTD @4425'.				
3. Stimulate perfs 4213 to 4347 w/1550 g 15% NEFE HCL acid				
4. RIH w/7" UNI VI pc pkr, XL on/off tool w/1.875 ss "F" nipple, 135 jts 2-7/8" Duoline tbg. Pkr set @4115'.				
5. Load csg w/100 bbl pkr fluid.				
6. Tst csg to 600 psi for 30 min and chart for the NMOCD.				
7. RDPU. Clean Location.				
Rig Up Date: 01/26/2006				
Rig Down Date: 01/31/2006				
-				
I hereby certify that the information above is true	and complete to the best of my know	ledge and belief. I further certify	that any pit or below-grade tank	has been/will be
constructed or		_		
closed according to NMOCD guidelines	, a general permit	or an (attached) alternativ	e OCD-approved	
DD + L	·11/2	plan		_
SIGNATURE Kolul Ho	lled	TITLE Workover Con	npletion Specialist DAT	E 01/03/2006
TYPE OR PRINT NAME Robert Gilbert	E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO	505/397-8206
APPROVED BY James W. 1	Nank	TITLE TO THE STATE OF	AT ATTACE WA	EED A 9 200
CONDITIONS OF APPROVAL IF ANY:	OC FIELD REPRES	ENIAHVE WANTE	TED V • 200	
· · · · · · · · · · · · · · · · · · ·		-		

