
Submit 3 copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DesoEnter 12 13 ve 1.2006

District Office	Elicity, Milicials and Natural	resources Department		Revised 1-1-89
OIL CONSERVATION DIVISION			WELL ARING	
P.O. Box 1980 Hobbs NM 88240		WELL API NO.		
P.O. Box 2088		30-025-33328		
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease	r [3]
DISTRICT III			STATE 🗹 FEE 🗌	
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No. 317230	
			31	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO			7. Lease Name or Unit Agreeme	supplying the property of the
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI			V.M. HENDERSON	
(FORM C-101) FOR SUCH PROPOSALS.			- V.M. HENDERSON	
1. Type of Well: OIL GAS OTHER SWD				
Official Control of the Control of t			8. Well No.	
2. Name of Operator CHEVRON USA INC			8. Well No. 15	
2 Address of Operator			9. Pool Name or Wildcat	
15 SMITH RD, MIDLAND, TX 79705			SWD SAN AN	IDRES
4. Well Location				
Unit Letter G: 1650 Feet From The NORTH Line and 1650 Feet From The EAST Line				
Continue 20	246	D 275 MA	4D44 1.5A	COLINITY
Section 30	Township21S	Range 37E N	MPMLEA	COUNTY
	10. Elevation (Show whether DF, Rk	(B, RT,GR, etc.) 3517' GL		
11. Charles	· · · · · · · · · · · · · · · · · · ·			No. of the last of
Check A	Appropriate Box to Indicate N	ature of Notice, Report	, or Other Data	
NOTICE OF INTENTION	ON TO:	SI	JBSEQUENT REPOR	T OF:
_	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CAS	
PERFORM REMEDIAL WORK				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND ABA	ANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEME	NT JOB	
OTHER:		OTHER:	CONVERT TO SWD #987	~
1-23-06: MIRU. UNSEAT PUMP. LD RODS. 1-24-06: PMP 30 BBLS TO KILL WELL. REL TAC. LD TBG. 1-25-06: TIH W/BIT, 177 JTS. TAG @ 5585. 1-26-06: TIH W/CIBP TO 5520. RUN CBL 5520-3000. RUN CBL 5520-4300. TIH IN 2 RUNS W/BAILER. 35' OF CMT. PERF 4570-80, 4586-96, 4754-64, 4778-88, 4830-40, 4848-58, 4878-88, 4948-58. 1-27-06: PERF 4400-10, 4414-24, 4456-66, 4474-84, 4540-50, 4554-64. TIH W/TBG. PULL UP TO 140 JTS. SET PKR @ 4268. 1-30-06: ACIDIZE 4400-4958 W/7000 GALS 15% ANTI-SLUDGE HCL. SET PKR @ 4350, 140 JTS. 1-31-06: SWABBING. 2-01-06: REL PKR. TIH W/IPC TBG. PU 139 JTS & PKR. EOT @ 4360. CIRC PKR FLUID. LATCH BACK ON. 2-02-06: RUN MIT TEST FOR NMOCD TO 550#. HELD. (ORIGINAL CHART & COPY OF CHART ATTACHED) RIG DOWN. FINAL REPORT 2-03-06: STARTED INJECTING 4300 BWPD @ 0 PSI.				
SIGNATURE XINSE	est to the best of myknowledge and belief. TITLE Re Denise Pinkerton	gulatory Specialist	DATE	2/7/2008 432-687-7375
7	Λ		· · · · · · · · · · · · · · · · · · ·	
APPROVED CONDITIONS OF APPROVAL, IF ANY:	ME TITLE OC FIELD REPR	esentative II/Staff I	MANAGER DATE DesoLIE	9-12∰3√81. ൗ ∩∩ድ



APIH. 30-025-33328 SECTEON-30 TISHED -215 RANGE -37E COLONY-LEA 30 MINUTE CHARGE TOP PERF CHARGE TOP PERF CHARGE HCharen IX , 2-2-06

U.M. HENDERSON #15

- PACKERO 4360'