Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-28564
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Fo. NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	LG-2670
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name  Dove VK State
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other P&A	8. Well Number
1. Type of Well: Oil Well Gas Well Other P&A	4
Name of Operator     Yates Petroleum Corporation	9. OGRID Number 025575
3. Address of Operator 105 S. 4 <sup>th</sup> Street, Artesia, NM 88210	10. Pool name or Wildcat Lazy J Penn & Baum; Wolfcamp, South
4. Well Location	
Unit Letter G: 1980 feet from the North line and	1980 feet from the <u>East</u> line
Section 3 Township 14S Range 33E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
4214.5' GR	
Pit or Below-grade Tank Application or Closure	
Pit type <u>Steel</u> Depth to Groundwater <u>N/A</u> Distance from nearest fresh water well <u>N/A</u>	Distance from nearest surface waterN/A
Pit Liner Thickness: N/A mil Below-Grade Tank: Volume N/A bbls;	Construction Material <u>N/A</u>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WOR	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	LLING OPNS. □ P & A □
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	т ЈОВ
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions or recompletion.	
1-31-06 MIRU WSU. POOH w/rods and tubing. Tubing stuck. Called OCD and received approval to cut tubing.	
2-1-06 Cut tubing @ 9333'. Worked TAC. TAC will not go down. Push TAC to bottom.	
2-3-06 Spotted 25 sx @ 9333'. WOC 4 hrs. Tgged @ 8604'. Tag ok'd by OCD. Circulated mud. PUH and spotted 50 sx @ 7736'.	
<b>2-6-06</b> Tagged @ 7334'. Perforated @ 5573'. Spotted 30 sx @ 5605'.	
2-7-06 Tagged @ 5446'. Perforated @ 4248'. Squeezed w/50 sx. WOC. Tagged @ 4200'. OCD wanted re-perf. Perforated @ 4190'. Tested to 1100#. OCD wanted re-perf @ 4140'. Perforated @ 4140'.	
2-8-06 Spotted 25 sx cement @ 4140'. WOC. Tagged @ 4106'. Perforated @ 2674'. Squeezed w/30 sx. WOC. Tagged @ 2640'. WOC 1 hr. Tagged @ 2610'. Ok'd by OCD. Perforated @ 1676'. Squeezed w/30 sx.	
2-9-06 Tagged @ 1547'. Perforated @ 512'. Squeezed w/30 sx. WOC and tagged @ 380'. Perforated @ 60'. Squeezed 20 sx to surface. Cut off wellhead and install marker and clean up location.  Approved as to plugging of the Well Bore.	
Liao	wility under bond is retained until ace restoration is completed.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURE TITLE Regulatory Compliance Technician DATE 2-16-06	
Type or print name Stormi Davis	
APPROVED BY: Your W. WIRE THILE IELD REPRESENTATIVE II/STAFF MANAGED THILE II/STA	
Conditions of Approval (if any):	