## OCD-HOBBS

## LINITED STATES

(JUNE 1990)	DEPARTME BUREAU OF		NTERIOR		FORM APPROVED  Budget Bureau No. 1004-0135  Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS					<ol> <li>Lease Designation and Serial No. NM-27805</li> </ol>
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT-" for such proposals					6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE					7. If Unit or CA, Agreement Designation
Type of Well Oil	Gas				
X Well Well Other					8. Well Name and No.
2. Name of Operator					Lechuza Federal #5
STRATA PRODUCTION COMPANY  3. Address and Telephone No. P. O. Box 1030					9. API Well No.
Roswell, New Mexico 88202-1030 505-622-1127					30-025-31801  10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Livingston Ridge Delaware East
1650' FSL & 330' FWL					11. County or Parish, State
Section 15-22S-32E					Lea County, New Mexico
12. CHECK	APPROPRIATE BOX	K(s) TO INDI	CATE NATURE O	F NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
	Notice of Intent	X	Abandonment	~~? <u>`</u>	Change of Plans
<del></del>			Recompletion	13	New Construction
X	Subsequent Report		Plugging Back	2324 Sign	Non-Routine Fracturing
			Casing Repair	32 25	Water Shut-Off
	Final Abandonment Notice		Altering Casing		Conversion to Injection
			OTHER		Dispose Water   (Note: Report results of multiple completion on Well
13. Describe Prop	osed or Completed Operations (Cle	arly state all pertinen	t details, and give pertinent dat	es, including estima	Completion or Recompletion Report and Log form.) ted date of starting any proposed work. If well is
directionally (	inited, give subsurface locations and	d measured and true	vertical depths for all markers a	and zones pertinent t	o this work.)*
12/29/05					P. POOH w/tbg. SI.
12/30/05	o: Run gauge to 70	cea to 1000#	SP at 7900°. Dump	35' cmt on t	op. RIH w/tbg to 6800'. Cir
10# mud. Test csg to 1000#. POOH and spot 25 sxs at 4580'. POOH to 3000'. SD. 01/02/06: RIH. Tag at 4320'. POOH w/tbg. NDWH. Weld on 5 1/2" Pull Nipple. Cut csg at 278					
	LD 65 jnts. NUE	3OP. SI well	,	.a 011 0 172 1	an Hippio. Out obg at 2700.
01/03/06: NUBOP. RIH and spot 35 sxs at 2836'. POOH. WOC. Tag at 2680'. POOH and					
			I and⁻spot 35 sxs a	it 660'. POC	OH. All plugs ok'd by Jim
01/04/06	McCormick w/Bl		: 00 ava at 60! ta ai	urfo o o Out o	off years bearing to the state of the state
01/04/00		evel location.	Empty steel pit. N	mace. Cut o Nove off	off wellhead. Install dry hole ACCEPTED FOR RECORD
			and the second s		TED TOT REGORD
	•				
					JAN 30 2006
•	•				
					LES BABYAK PETROLEUM ENGINEER
	tify that the foregoing is true a				L CHOCCOM ENGINEER
Signed	Lun Mritt	Tit!	e Production Reco	rds	Date 01/18/06

Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title



(This space for Federal or State office use)

Conditions of approval, if any:

Approved by

Date