

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	30-025-23388
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. K-1860	
7. Lease Name or Unit Agreement Name Atlantic 32 State	
8. Well Number #01	
9. OGRID Number #010179	
10. Pool name or Wildcat Buffalo; Queen	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐  
2. Name of Operator  
HARVEY E. YATES COMPANY  
3. Address of Operator  
PO BOX 1933  
ROSWELL NM 88202

4. Well Location  
Unit Letter C : 660' feet from the North line and 1,980' feet from the West line  
Section 32 Township 18S Range 33E NMPM County Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3,754' GL

Pit or Below-grade Tank Application ☐ or Closure ☐ **We will use a frac tank - no pit will be necessary.**

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

We propose to plug and abandon this well as follows:

1. Spot 100' plug at 4,400' - 4,300'.
2. Circulate 8# mud.
3. Set 100' cement plug from 2,970' - 3,070'. Tag.
4. Cut 5 1/2" csg at approx 1,950' (TOC @ 1,970').
5. Spot 100' cement from 1,900' - 2,000' (50' in & out of cut csg). Tag.
6. Spot 100' cement at 13 3/8" csg shoe from 400' - 500'. Tag.
7. Spot 25 sx surface plug and set dry hole marker.



**THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☒.

SIGNATURE Jen Serrano TITLE PRODUCTION ANALYST DATE 2/21/2006

Type or print name \_\_\_\_\_ E-mail address: jserrano@nms.gov Telephone No. 505.623.6601

**For State Use Only**

APPROVED BY: Gay W. Wink TITLE FIELD REPRESENTATIVE DATE FEB 27 2006

Conditions of Approval (if any): G1