

Submit 3 Copies to Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-37407
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator MARBOB ENERGY CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator PO BOX 227, ARTESIA, NM 88211-0227		7. Lease Name or Unit Agreement Name FORGOTTEN STATE
4. Well Location Unit Letter <u>E</u> : <u>2310</u> feet from the <u>NORTH</u> line and <u>330</u> feet from the <u>WEST</u> line Section <u>24</u> Township <u>16S</u> Range <u>33E</u> NMPM County <u>LEA</u>		8. Well Number <u>2</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4166' GL		9. OGRID Number 14049
Pit or Below-grade Tank Application ☐ or Closure ☐		10. Pool name or Wildcat HUME; QUEEN, WEST
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☒
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUGGED & ABANDONED AS FOLLOWS:

2/15/06 - SET CIBP @ 3625'. RIH OPENED & CIRC CSG FULL OF 9 PPG PLUGGING MUD CONT 25 PPB SALT GEL. SPOT 40 SX CLASS "C" W/ 2% CACL2 ON TOP OF CIBP @ 3625'. SPOT 25 SX CLASS "C" W/ 2% CACL2 @ 1550'. SPOT 50 SX CLASS "C" W/ 2% CACL2 @ 450'. FINISH FILLING UP 8 5/8" CSG. CUT OFF 8 5/8" WELLHEAD. INSTALL OCD APPROVED DRY HOLE MARKER.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE: Diana J. Briggs TITLE: PRODUCTION ANALYST DATE: 2/17/06

Type or print name DIANA J. BRIGGS
For State Use Only

E-mail address: PRODUCTION@MARBOB.COM Telephone No. (505) 748-3303

APPROVED BY: Chris Williams TITLE: Risk Mgr. DATE: 3/1/06
Conditions of Approval (if any):