Submit 3 copies

State of New Mexico

to Appropriate District Office	Energy, Minerals and Natural Resources Department	Revised 1-1-89
DISTRICT I	OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088	30-025-07001
DISTRICT II	Santa Fe. New Mexico 87504, 2088	5. Indicate Type of Lease
P.O. Box Drawer DD, Artesia, NM 88210	Canta 1 C, 11CW MCXICO 07004-2000	STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil / Gas Lease No.
	TICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name
	RVOIR. USE "APPLICATION FOR PERMI C-101) FOR SUCH PROPOSALS.	MARK OWEN
1. Type of Well: OIL GAS		
WELL WEI		
2. Name of Operator : CHEVRON !	ICA INIC	8. Well No.
		O Pool Name on Wildoot
3. Address of Operator 15 SMITH F	RD, MIDLAND, TX 79705	9. Pool Name or Wildcat PENROSE SKELLY GRAYBURG
4. Well Location		
Unit Letter <u>J</u> : <u>1980'</u> Feet From The <u>SOUTH</u> Line and <u>1980'</u> Feet From The <u>EAST</u> Line		
Section 34	Township21-S Range37-ENI	MPMLEA_COUNTY
4	10 Floreties (Chausahathat DE BVB DT CD ata)	
	3426' DF	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION	ON TO:	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OP	PERATION PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEME	NT JOB
OTHER:	OTHER:	ACIDIZE & SCALE SQZ ✓
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-03-06: MIRU. JAR ON PUMP, PUMP STUCK. 2-06-06: TIH W/BIT TO 3773. POOH TO 2724. 2-07-06: TIH W/BIT & TAG @ 3773. DRILL OUT TO 3844. SPOT 1000 GALS XYLENE & DISPL 16 BBLS. POOH TO 2750. 2-08-06: PUMP 30 BBLS OF KILL FLUID. POOH TO 1453. 2-09-06: TIH W/PKR. PUMP KILL FLUID DN CSG & TBG. TIH W/PKR TO 3565, 112 JTS. LOAD & TEST CSG TO 350#. OK. 2-10-06: ACIDIZEI-OPENHOLE 3600-3844 W/5500 GALS NEFE HCL & SALT. 2-13-06: TBG PRESS-240#. 2-14-06: WELL FLOWING. SWAB. 2-15-06: TOH W/PKR. 2-16-06: TIH W/BIT TO 3804. TAG SALT. POOH TO 3504. TIH TO 3804. WASH DN TO 3844. POOH TO 3504. 2-17-06: TIH W/BIT TO 3834. WASH DOWN TO 3844. PMP DN TBG W/50 BBLS 2% KCL & 200 BBLS 8.6 CUT BRINE. 2-21-06: TIH W/BIT TO 3834. WASH DOWN TO 3844. PMP DN TBG W/50 BBLS 2% KCL & 200 BBLS 8.6 CUT BRINE. 2-21-06: TIH W/13 JTS 2 7/8" TBG. 2-22-06: TIH W/111 JTS TBG, TAC, 6 JTS, IPC JT, SN, DESANDER, 2 JTS, VALVE TRY TO SET TAC. WOULD NOT SET. PULL & TIMES TILL EOT @ CSG SHOE. TAC WOULD NOT SET. 2-23-06: TOH W/2 7/8" TBG TO TAC, 112 JTS. TIH & ADD 3 JTS BELOW TAC. PROD TBG, EOT @ 3816. TIH W/PMP & RODS. 2-24-06: RIG DOWN. FINAL REPORT		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE DEMISE IMA	LETON TITLE Regulatory Specialist	DATE 2/27/2006
	Penise Pinkerton	Telephone No. 432-687-7375

OC MELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 1 4 2006 MAR 1 4 2006