

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-25674
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-8667-2
7. Lease Name or Unit Agreement Name State AR
8. Well Number 1
9. OGRID Number 16696
10. Pool name or Wildcat Vacuum Abn, Worth
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3980'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
OXY USA Inc.

3. Address of Operator
P.O. Box 50250 Midland, TX 79710

4. Well Location
Unit Letter B : 470 feet from the North line and 1990 feet from the east line
Section 30 Township 17S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3980'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING <SWD INJECTION> CONVERSION ☐ RBDMS ☐ RETURN TO ☐ TA ☐ CSNG ☐ ENVIRO ☐ CHG LOC ☐ INT TO PA ☐ P&A NR ☒ P&A R ☐ CLOSED-LOOP SYSTEM ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ P AND A ☒ CASING/CEMENT JOB ☐ OTHER: ☐
---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15. MAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/7/2015 MIRU PU

10/8/2015 Start to POOH w/ rods & pump, rods parted. NU BOP on WH, work on unseating TAC, start to POOH w/ tbq.

10/9/2015 Continue to POOH w/ 2145' tbq, unseat pump, POOH w/ rods & pump.

10/12/2015 Continue to POOH w/ tbq. RIH w/ CIBP & set @ 8530'. RIH & tag CIBP @ 8350'

10/13/2015 Circ hole w/ 10# MLF, M&P 35sx CL Cmt, calc TOC 8057'. PUH to 7553', M&P 25sx CL Cmt, PUH, WOC. RIH & tag cmt @ 7095', PUH to 6077', M&P 25sx CL Cmt, PUH, WOC.

10/14/2015 RIH & tag cmt @ 5703', PUH to 4501', M&P 30sx CL Cmt, PUH, WOC. RIH & tag cmt @ 4018'. RIH w/ pkr & isolate holes @ 1340-1370', RIH & set pkr @ 3470'. RIH & perf @ 3840', attempt to EIR, pressured up to 1500#, no rate. Rec approval from Mark Whitaker-NMOCD to spot plug. RIH to 3900', M&P 25sx CL Cmt, PUH, WOC.

10/15/2015 RIH & tag cmt @ 3530', PUH & set pkr @ 2556', RIH & perf @ 2950', attempt to EIR, well pressured up to .5BPM @ 1500#. Contact Mark Whitaker-NMOCD, requested to attempt to re-perf @ intermediate shoe. RIH & perf @ 2950', well pressured up to 1BPM @ 1350#, etc approval to spot plug. RIH to 2980', M&P 50sx CL Cmt, PUH, set pkr @ 2000', rev circ tbq, sqz 7bbl into perfs, displace to 2700', ISIP-1500#.

10/16/2015 RIH & tag cmt @ 2730', PUH, EIR, M&P 60sx CL Cmt @ 1340-1370', WOC. RIH & tag cmt @ 1166', PUH & set pkr @ 30', RIH & perf @ 350', EIR, M&P 120sx CL Cmt, circ cmt to surface, visually confirmed. RD BOP, top off csg, RDPU.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Sr. Regulatory Advisor

DATE

10/19/15

Type or print name

David Stewart

E-mail address:

david_stewart@oxy.com

PHONE:

432-685-5717

For State Use Only

APPROVED BY:

Mark Brown

TITLE

Dist. Supervisor

DATE

10/26/2015

Conditions of Approval (if any):

OCT 27 2015